

OBJECTID	APS_ButtonPush button <=5' of outside edge of cross walk?	Push button face oriented parallel w/ crosswalk?	Is there a level landing 4" x 4" adj to push button?	Push button btwn 1.5' and 10' from back of curb?	Is there 10' of separation between push buttons?	Push button mounted between 42" and 48"?	Is a 4' PAR w/ 2% cross slope maintained?	Is there an audible walk indication?	Is there a vibrotactile arrow present and pointed in the correct direction?	Notes	last_edited_date	# of Non Compliant	Overall Compliant	Jurisdiction
2	1	1	1	1	0	1	1	1	1		6/25/2018	1	NO	State
3	1	1	1	1	1	1	1	1	1		6/25/2018	0	YES	State
4	1	1	1	1	1	1	1	1	1		6/25/2018	0	YES	State
5	1	1	1	1	0	1	1	1	1		6/25/2018	1	NO	State
6	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
7	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
8	1	1	1	1	0	1	1	1	1		6/26/2018	1	NO	State
9	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
10	1	1	1	1	1	0	1	1	1	40" to button	6/26/2018	1	NO	State
11	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
12	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
13	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
14	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
15	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
16	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
17	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
18	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
19	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
20	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
21	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
22	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
23	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
24	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
25	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
26	1	1	1	0	0	1	1	1	1	13' from boc and 9 ft 10 inches apart	6/26/2018	2	NO	State
27	1	1	1	1	0	1	1	1	1	9' 10"	6/26/2018	1	NO	State
28	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
29	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
30	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
32	1	1	1	1	0	1	1	1	0	7ft between push buttons. Pointing more to the left of the intersection.	6/26/2018	2	NO	State
33	1	1	1	1	1	1	1	1	0	slightly angled off	6/26/2018	1	NO	State
34	1	1	1	1	0	1	1	1	1	7ft between push buttons. Pointing more towards the left of the intersection.	6/26/2018	1	NO	State
35	1	1	1	1	0	1	1	1	1	9.5 ft of separation	6/26/2018	1	NO	State
36	1	1	1	1	0	1	1	1	1	9.5 ft of separation	6/26/2018	1	NO	State
37	1	1	1	1	1	1	1	1	1		6/26/2018	0	YES	State
38	1	1	0	1	1	0	1	1	0	Arrow is pointing towards the right instead of straight across to the next pedestrian crosswalk. 39"	6/26/2018	3	NO	State
39	1	1	1	1	0	1	1	0	0		6/29/2018	3	NO	Local
40	1	1	1	1	1	1	1	0	0		6/29/2018	2	NO	Local
41	0	1	1	0	0	1	0	0	0		6/29/2018	6	NO	Local
42	1	1	1	1	0	1	0	0	0		6/29/2018	4	NO	Local
43	1	1	1	0	0	1	1	0	0		6/29/2018	4	NO	Local

OBJECTID	APS_ButtonPush button <=5' of outside edge of cross walk?	Push button face oriented parallel w/ crosswalk?	Is there a level landing 4" x 4" adj to push button?	Push button btwn 1.5' and 10' from back of curb?	Is there 10' of separation between push buttons?	Push button mounted between 42" and 48"?	Is a 4' PAR w/ 2% cross slope maintained?	Is there an audible walk indication?	Is there a vibrotactile arrow present and pointed in the correct direction?	Notes	last_edited_date	# of Non Compliant	Overall Compliant	Jurisdiction
44	1	1	1	1	0	1	1	0	0	sign and button on opposite side of signal pole	6/29/2018	3	NO	Local
45	1	1	1	1	0	1	1	0	0		6/29/2018	3	NO	Local
46	1	1	1	1	0	1	1	0	0		6/29/2018	3	NO	Local

TOTAL:	44
# Compliant:	24
% Compliant:	55%

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
4	1	1	3.6	1	0.1	0	1	1.2	1	0	0	0	1	Fair	Water gate valve in landing of sidewalk.	6/26/2018	4	NO	Local
5	1	1	4.8	1	0	1	0	2.2	1	1	1	1	1	Fair		6/26/2018	1	NO	Local
6	1	1	1.8	1	1.3	1	0	2.2	1	0	0	0	1	Good		6/26/2018	4	NO	Local
7	1	1	7.0	1	.4	1	1	.9	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
8	1	1	7.5	1	1.0	1	1	.9	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
9	1	1	6.7	1	1.3	0	1	1.3	1	0	0	0	1	Fair	Vegetation growth in the cracks of the curb ramp.	6/26/2018	4	NO	Local
10	1	1	5.5	1	0.4	0	1	1.3	1	0	0	0	1	Fair	Vegetation growth in the cracks of the curb ramp.	6/26/2018	4	NO	Local
11	1	1	1.8	1	1.6	0	1	1.0	1	0	0	0	1	Poor	Vegetation growth in the cracks of the curb ramp.	6/26/2018	4	NO	Local
12	1	1	6.0	1	0.3	1	1	1.1	1	0	0	0	1	Poor	Vegetation growth in the cracks of the curb ramp.	6/26/2018	3	NO	Local
13	1	1	5.5	1	0.4	0	1	1.4	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
14	1	1	4.8	1	1.0	0	1	1.6	1	0	0	0	0	Fair		6/26/2018	5	NO	Local
15	1	1	5.1	1	1.3	1	1	1.3	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
16	1	1	.5	1	.2	1	1	.9	1	1	1	1	1	Good		6/26/2018	0	YES	State
17	1	1	0.9	1	0.5	1	1	0.9	1	1	1	1	1	Good		6/26/2018	0	YES	State
18	1	1	0.1	1	0.6	1	1	0.7	1	1	1	1	1	Good	Electric manhole and vault in the sidewalk.	6/26/2018	0	YES	State
19	1	1	.8	1	.1	1	1	.7	1	1	1	1	1	Good	electric box by ramp	6/26/2018	0	YES	State
20	1	1	0.7	1	0.7	1	1	1.2	1	1	1	1	0	Good	Manhole and electric vault in the sidewalk.	6/26/2018	1	NO	State
21	1	1	.8	1	.7	1	1	1.2	1	1	1	1	1	Good	manhole in landing	6/26/2018	0	YES	State
22	1	1	1.0	1	0.1	1	1	0.9	1	1	1	1	1	Good	Manhole and vault in the sidewalk.	6/26/2018	0	YES	State
23	1	1	.6	1	.3	1	0	.9	1	1	1	1	1	Good		6/26/2018	1	NO	State
24	1	1	3.3	1	.7	1	1	.7	1	0	0	0	1	Fair	utility in ramp area	6/26/2018	3	NO	Local
25	1	1	4.1	1	1.0	1	1	.7	0	0	0	0	1	Fair		6/26/2018	4	NO	Local
26	1	1	3.1	1	1.4	1	0	no landing	1	0	0	0	1	Fair	brick	6/26/2018	4	NO	Local
27	1	1	2.6	1	1.8	1	0	no landing	1	0	0	0	1	Fair	brick and leading to sidewalk connection is bad	6/26/2018	4	NO	Local
28	1	1	3.3	1	.6	1	0	2.7	1	0	0	0	1	Fair	little gap onto city hall prop	6/26/2018	4	NO	Local
29	1	1	3.6	1	.1	1	0	3.2	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
30	1	1	2.2	1	.1	1	0	no landing	0	0	0	0	0	Poor	large gaps greater than 1.5 inches	6/26/2018	6	NO	Local
31	1	1	.3	1	1.0	1	0	no landing	1	0	0	0	1	Poor	its brick so very unlevel	6/26/2018	4	NO	Local
32	1	1	1.5	1	1.0	1	0	no landing	0	0	0	0	1	Fair		6/26/2018	5	NO	Local
33	1	1	3.5	1	.3	1	0	3.3	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
34	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	Local
35	1	1	3.1	1	1.6	1	1	0.7	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
36	1	1	3.2	1	1.4	1	1	1.7	1	0	0	0	1	Fair	brick	6/26/2018	3	NO	Local
37	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	Local
38	1	1	4.3	1	0.0	1	1	2.0	1	0	0	0	1	Fair	brick	6/26/2018	3	NO	Local
39	1	1	4.6	1	.5	1	1	1.0	1	1	1	1	1	Good		6/26/2018	0	YES	Local
41	1	1	2.9	1	3.8	0	1	1.8	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
42	1	1	3.0	1	1.4	1	1	1.8	1	0	0	0	1	Fair	chunk of sidewalk missing	6/26/2018	3	NO	Local
43	1	1	1.1	1	1.1	1	1	1.4	1	0	0	0	1	Good		6/26/2018	3	NO	Local
44	0	1	0.4	1	0.5	0	1	0.5	0	0	0	0	1	Good	This is not a curb ramp it is a sidewalk	6/26/2018	6	NO	Local
45	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
46	1	1	3.4	1	0.2	1	0	1.0	1	0	1	1	1	Good	Landing is not 48"x48"	6/28/2018	2	NO	Local
47	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
48	1	1	.8	1	1.9	1	0	3.2	1	1	1	1	1	Good		6/28/2018	1	NO	Local
49	1	1	5.3	1	.5	1	1	1.6	1	1	1	1	1	Good		6/28/2018	0	YES	Local
50	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
51	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
52	1	0	8.4	1	2.0	1	1	2.0	0	1	1	1	1	Good		6/28/2018	2	NO	Local
53	1	1	3.7	1	0.2	1	1	1.0	1	0	1	1	1	Good		6/28/2018	1	NO	Local
54	1	1	3.2	1	0.7	1	1	1.5	1	0	1	1	1	Good		6/28/2018	1	NO	Local
55	1	1	2.6	1	.4	1	1	1.7	1	0	1	1	1	Good		6/28/2018	1	NO	Local
56	1	1	1.7	1	1.6	1	1	1.8	0	1	1	1	1	Good		6/28/2018	1	NO	Local
57	1	1	3.5	1	0.4	1	1	1.6	1	0	1	1	1	Good		6/28/2018	1	NO	Local
58	1	1	2.8	1	1.2	1	1	1.7	1	0	1	1	1	Good		6/28/2018	1	NO	Local
59	1	1	2.4	1	1.2	1	1	1.7	1	1	1	1	1	Good		6/28/2018	0	YES	Local
60	1	1	5.4	0	3.2	1	0	4.1	0	0	0	0	1	Fair	no det panels	6/28/2018	6	NO	Local
61	1	1	4.2	1	.2	1	0	.7	0	0	0	0	1	Fair	gap on roadway	6/28/2018	5	NO	Local
62	1	1	4.3	1	0.9	1	1	1.1	1	0	1	1	1	Good		6/28/2018	1	NO	Local
63	1	1	2.0	1	0.4	1	1	1.1	1	0	1	1	1	Good		6/28/2018	1	NO	Local
65	1	1	6.3	1	0.0	1	1	2.1	1	0	1	1	1	Good		6/28/2018	1	NO	Local
66	1	1	5.2	1	.3	1	1	1.5	1	1	1	1	1	Good		6/28/2018	0	YES	Local
67	1	1	2.1	1	.8	1	1	1.5	0	1	1	1	1	Good		6/28/2018	1	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
68	1	1	3.1	1	0.8	1	1		1	0	1	1	1	Good	1.0	6/28/2018	1	NO	Local
69	1	1	2.8	1	1.0	1	1	1.0	1	0	1	1	1	Good		6/28/2018	1	NO	Local
70	1	1	4.5	1	1.6	1	1	2.0	0	1	1	1	1	Good		6/28/2018	1	NO	Local
71	1	1	4.6	1	.4	1	1	1.5	0	1	1	1	1	Good		6/28/2018	1	NO	Local
72	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
73	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
74	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
75	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
76	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
77	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
78	1	1	8.0	0	2.2	1	0	3.7	0	1	1	1	1	Good		6/28/2018	3	NO	Local
79	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
80	1	1	4.9	1	1.9	1	1	.9	0	1	1	1	1	Good		6/28/2018	1	NO	Local
81	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
82	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
83	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
84	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
85	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
86	1	1	5.4	1	.6	1	1	2.3	0	0	1	1	1	Good		6/28/2018	3	NO	Local
87	1	1	5.4	1	.7	1	1	.9	0	1	1	1	1	Good		6/28/2018	1	NO	Local
88	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
89	1	1	2.4	1	.1	1	1	1.1	0	0	1	1	1	Good		6/29/2018	2	NO	Local
90	1	1	3.2	1	.2	1	1	1.7	0	0	1	1	1	Good		6/29/2018	2	NO	Local
91	1	1	5.4	1	.1	0	1	1.8	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
92	1	1	2.6	1	.3	1	1	1.8	0	1	1	1	1	Good		6/29/2018	1	NO	Local
93	1	1	3.0	1	.4	1	1	.8	0	1	1	1	1	Good		6/29/2018	1	NO	Local
94	1	1	5.4	1	0.0	0	1	.8	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
95	1	1	5.9	1	0.9	0	1	1.2	1	0	0	0	0	Fair	1.5" or greater gap	6/29/2018	5	NO	Local
96	1	1	5.4	1	0.0	1	1	1.2	1	0	0	0	0	Fair	1.5" or greater gap	6/29/2018	4	NO	Local
97	1	1	5.9	1	0.3	1	1	1.1	1	0	1	1	1	Good		6/29/2018	1	NO	Local
98	1	1	5.4	1	0.1	1	1	1.1	1	0	1	1	1	Good		6/29/2018	1	NO	Local
99	1	1	5.8	1	1.1	1	0	2.2	1	0	0	0	0	Fair	The curb ramp and sidewalk does not connect. Missing a panel.	6/28/2018	5	NO	Local
100	1	1	4.9	0	3.6	1	0	4.0	0	0	1	1	1	Good		6/28/2018	4	NO	Local
101	1	1	5.4	0	2.1	1	0	3.2	0	1	1	1	1	Good		6/28/2018	3	NO	Local
103	1	1	2.0	1	.5	1	1	2.0	1	1	1	1	1	Good		6/26/2018	0	YES	Local
104	1	1	3.4	1	1.4	1	1	0.3	1	0	0	0	0	Poor		6/26/2018	4	NO	Local
105	1	1	1.4	1	.3	1	0	no landing	1	1	1	1	1	Good		6/26/2018	1	NO	Local
106	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
107	1	1	2.8	1	0.0	1	1	2.0	1	0	0	0	1	Fair		6/28/2018	3	NO	Local
108	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
110	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
111	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
112	1	0		0		0	0		0	0	0	0	0			6/28/2018	9	NO	Local
113	1	1	7.6	1	0.1	1	1	1.5	1	0	0	0	1	Fair		6/28/2018	3	NO	Local
114	1	1	2.6	1	0.2	0	0	2.3	1	0	1	1	1	Good		6/28/2018	3	NO	Local
115	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
116	1	1	2.5	1	0.1	1	1	0.8	1	0	1	1	1	Good		6/28/2018	1	NO	Local
117	1	0	15.6	1	.8	1	1	.6	1	0	0	0	1	Fair		6/28/2018	4	NO	Local
118	1	1	3.6	1	0.2	1	1	0.7	1	0	1	1	1	Good		6/28/2018	1	NO	Local
119	1	1	2.5	1	0.8	1	1	0.3	1	0	1	1	1	Good		6/28/2018	1	NO	Local
120	1	1	1.6	1	0.7	1	1	0.7	1	0	1	1	1	Good		6/28/2018	1	NO	Local
121	1	1	2.9	1	0.1	1	1	0.3	1	0	1	1	1	Good		6/28/2018	1	NO	Local
122	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
123	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
124	1	1	2.5	1	.5	1	1	1.8	1	1	1	1	1	Good		6/28/2018	0	YES	Local
125	1	1	2.8	1	.5	1	1	1.8	1	0	1	1	1	Good		6/26/2018	1	NO	Local
126	1	1	4.5	1	1.5	1	1	1.5	0	1	1	1	1	Good		6/28/2018	1	NO	Local
127	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
128	1	1	1.7	1	0.1	1	1		1	0	1	1	1	Good		6/28/2018	1	NO	Local
129	1	1	2.4	1	0.1	1	0	0.7	1	0	1	1	1	Good		6/28/2018	2	NO	Local
130	1	1	2.0	1	0.2	1	1	0.7	1	0	1	1	1	Good		6/28/2018	1	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
131	1	1	1.9	1	0.5	1	0	2.1	1	1	1	1	1	1	Good	6/26/2018	1	NO	Local
132	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	Local
133	1	1	6.1	1	.3	1	1	1.9	0	0	0	0	1	Fair		6/26/2018	4	NO	Local
134	1	1	5.6	1	0.5	1	0	2.4	1	0	0	0	1			6/26/2018	4	NO	Local
135	1	1	2.3	1	.1	1	1	.9	1	1	1	1	1	Good		6/26/2018	0	YES	Local
136	1	1	.7	1	.7	1	1	.9	1	1	1	1	1		very sandy	6/26/2018	0	YES	State
137	1	1	.4	1	.8	1	1	.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
140	1	1	5.0	1	.4	1	1	.8	0	1	1	1	1	Good		6/26/2018	1	NO	Local
141	1	1	4.4	1	.1	1	1	.6	0	1	1	1	1	Good		6/26/2018	1	NO	Local
142	1	1	3.5	1	.4	1	1	.6	1	1	1	1	1	Good		6/26/2018	0	YES	State
143	1	1	1.0	1	.6	1	1	.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
144	1	1	2.0	1	.3	1	1	.8	1	1	1	1	1	Good		6/26/2018	0	YES	Local
145	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	Local
146	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	Local
147	1	1	6.7	1	.9	1	1	1.3	0	1	1	1	1	Good		6/28/2018	1	NO	Local
148	1	1	5.9	1	0.2	1	1	1.0	1	1	1	1	1	Good		6/28/2018	0	YES	Local
149	1	1	4.4	1	.7	1	1	1.0	0	1	1	1	1	Good		6/28/2018	1	NO	Local
151	1	0	10.1	1	.3	0	0	2.1	0	0	0	0	1	Fair		6/28/2018	7	NO	Local
152	1	0	12	1	.8	1	1	.3	0	0	0	0	1	Fair		6/28/2018	5	NO	Local
153	1	1	8.1	1	0.3	1	1	0.3	1	0	0	0	1	Fair		6/28/2018	3	NO	Local
154	1	0	16.8	1	.3	1	0	4.5	1	0	0	0	1	Fair		6/28/2018	5	NO	Local
155	1	0	10.1	0	2.4	1	0	2.7	1	0	0	0	1	Fair		6/28/2018	6	NO	Local
156	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
158	1	1	7.9	0	2.8	0	0	2.5	1	0	0	0	1	Fair		6/28/2018	6	NO	Local
159	1	1	6.9	1	.5	1	0	2.5	0	1	1	1	1	Good		6/28/2018	2	NO	Local
160	1	1	4.7	1	1.6	1	1	1.1	0	1	1	1	1	Good		6/28/2018	1	NO	Local
161	1	1	6.1	1	.6	1	1	1.1	0	1	1	1	1	Good		6/28/2018	1	NO	Local
162	1	1	2.0	1	.7	1	1	.7	0	0	0	0	1	Fair		6/28/2018	4	NO	Local
163	1	1	4.2	1	.9	1	1	.7	0	0	0	0	1	Fair		6/28/2018	4	NO	Local
164	1	0	8.8	1	.8	0	1	1.3	0	0	0	0	1	Fair		6/28/2018	6	NO	Local
165	1	0	10.8	1	1.6	0	1	1.3	0	0	0	0	1	Fair		6/28/2018	6	NO	Local
166	1	1	6.3	1	1.1	1	1	.6	0	1	1	1	1	Good		6/28/2018	1	NO	Local
167	1	1	5.4	1	2.0	1	1	.6	0	1	1	1	1	Good		6/28/2018	1	NO	Local
168	1	1	4.5	0	2.1	1	1	1.8	0	1	1	1	1	Good		6/28/2018	2	NO	Local
169	1	1	4.6	1	1.8	1	1	1.8	0	1	1	1	1	Good		6/28/2018	1	NO	Local
170	1	1	4.1	0	3.9	1	1	1.2	0	1	1	1	1	Good		6/28/2018	2	NO	Local
171	1	1	3.0	1	.3	1	1	1.2	0	1	1	1	1	Good		6/28/2018	1	NO	Local
172	1	1	7.1	1	.5	1	1	1.0	0	1	1	1	1	Good		6/28/2018	1	NO	Local
173	1	1	6.4	1	.2	1	1	1.5	0	1	1	1	1	Good		6/28/2018	1	NO	Local
174	1	1	4.3	1	.9	1	1	1.5	0	1	1	1	1	Good		6/28/2018	1	NO	Local
176	1	1	4.6	1	0.2	1	1	1.9	1	0	1	1	1	Good		6/28/2018	1	NO	Local
177	1	1	5.1	1	.3	1	1	.6	1	1	1	1	1	Good		6/28/2018	0	YES	Local
178	1	1	3.0	1	.1	1	1	.6	0	1	1	1	1	Good		6/28/2018	1	NO	Local
180	1	1	1.1	1	.5	1	1	1.9	0	1	1	1	1	Good		6/26/2018	1	NO	Local
181	1	0	12.1	1	3.0	1	0	1.3	1	0	0	0	0	Fair		6/26/2018	6	NO	State
182	1	1	3.2	1	1.1	1	1	1.5	1	0	1	1	1	Good		6/26/2018	1	NO	State
183	1	1	4.1	1	3.2	1	0	2.5	1	1	1	1	1	Good		6/26/2018	1	NO	Local
185	1	1	3.2	1	2.3	1	0	3.4	1	0	0	0	0	Fair		6/26/2018	5	NO	Local
187	1	1	2.3	1	0.6	1	1	0.6	1	0	0	0	1	Fair		6/28/2018	3	NO	Local
188	1	1	2.0	1	0.4	1	1	0.6	1	0	0	0	0	Fair		6/28/2018	4	NO	Local
189	1	1	2.1	1	1.9	1	1	1.8	0	0	0	0	1	Fair		6/26/2018	4	NO	Local
190	1	1	2.9	1	0.0	1	1	1.8	0	0	0	0	1	Fair		6/26/2018	4	NO	Local
192	1	0	3.5	1	.2	1	1	1.6	0	0	0	0	1	Fair		6/28/2018	5	NO	Local
193	1	1	5.3	1	.5	1	1	1.6	0	0	0	0	1	Fair		6/28/2018	4	NO	Local
195	1	1	5.2	1	1.4	1	1	1.1	0	0	0	0	1	Fair		6/28/2018	4	NO	Local
196	1	1	5.7	1	0.8	1	1		1	0	0	0	1	Fair		6/28/2018	3	NO	Local
197	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
198	1	1	3.5	1	0.5	1	1	1.2	1	0	0	0	0	Fair		6/28/2018	4	NO	Local
199	1	1	4.0	1	0.6	1	1	0.4	1	0	0	0	1	Fair		6/28/2018	3	NO	Local
200	1	1	3.8	1	0.6	1	1	0.4	1	0	0	0	1			6/28/2018	3	NO	Local
201	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
202	1	1	4.9	1	0.4	1	0	2.1	1	0	0	0	1	Fair		6/28/2018	4	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
203	1	1	4.5	1	0.3	1	1	1.7	1	0	0	0	1	Fair		6/28/2018	3	NO	Local
204	1	1	7.3	0	3.4	1	1	1.7	1	0	0	0	1			6/28/2018	4	NO	Local
205	1	1	6.9	1	.8	1	1	1.1	1	1	1	1	1	Good		6/28/2018	0	YES	Local
206	1	0	8.4	1	1.9	0	1	1.1	0	1	1	1	1	Good		6/28/2018	3	NO	Local
207	1	1	4.2	1	0.8	1	0	0.1	1	0	1	1	1	Good		6/28/2018	2	NO	Local
208	1	1	4.7	1	0.3	1	1	0.1	1	1	1	1	1	Good		6/28/2018	0	YES	Local
209	1	1	5.0	1	1.7	1	1	1.4	1	0	0	0	0	Fair		6/28/2018	4	NO	Local
210	1	1	4.4	1	.9	1	0	1.6	0	0	0	0	1	Fair	utility box is landing	6/28/2018	5	NO	Local
211	1	1	2.9	1	.8	1	1	1.6	0	0	0	0	1	Fair	utility box as landing	6/28/2018	4	NO	Local
212	1	1	2.2	1	0.3	1	0	2.5	1	0	1	1	1	Good	Electric Vault	6/28/2018	2	NO	Local
213	1	1	4.7	1	.3	1	0	2.5	1	1	1	1	1	Good	vault in landing	6/28/2018	1	NO	Local
215	1	1	5.1	1	0.8	1	1	1.4	1	0	0	0	1	Fair		6/28/2018	3	NO	Local
216	1	1	3.6	1	1.4	1	1	2.0	0	1	1	1	1	Fair		6/28/2018	1	NO	Local
217	1	1	3.9	1	.3	1	1	2.0	0	0	0	0	1	Fair		6/28/2018	4	NO	Local
218	1	1	3.9	0	2.3	1	0	2.1	0	0	1	1	1	Good		6/28/2018	4	NO	Local
220	1	0	6.2	1	1.0	1	0	1.4	1	0	0	0	1	Fair		6/28/2018	5	NO	Local
221	1	1	6.5	1	2.4	1	0	1.4	1	0	0	0	1	Fair		6/28/2018	4	NO	Local
222	1	1	4.6	1	.6	1	1	.8	0	0	0	0	1	Fair		6/28/2018	4	NO	Local
223	1	1	3.5	1	0.6	1	1	0.8	1	0	0	0	1			6/28/2018	3	NO	Local
224	1	1	2.1	1	.6	1	1	1.4	0	0	0	0	1	Fair		6/28/2018	4	NO	Local
225	1	1	3.7	1	.6	1	1	1.4	0	0	0	0	1	Fair		6/28/2018	4	NO	Local
226	1	1	6.4	0	5.0	1	1	1.7	0	1	1	1	0	Fair	lip by curb line and by landing	6/28/2018	3	NO	Local
227	1	1	3.5	1	.2	1	1	1.4	0	1	1	1	1	Good		6/28/2018	1	NO	Local
228	1	1	7.0	1	0.6	1	1	1.4	1	0	1	1	1	Good		6/28/2018	1	NO	Local
229	1	1	6.0	1	0.0	1	0	2.2	0	0	0	0	1	Fair	utility box in landing	6/29/2018	5	NO	Local
230	1	1	5.5	1	0.2	1	1	0.6	1	0	1	1	0	Good	1.5" gap or greater at the back of curb and curb ramp	6/28/2018	2	NO	Local
232	1	1	3.5	1	.5	1	1	.3	0	1	1	1	1	Good	1 inch lip by curb	6/28/2018	1	NO	Local
233	1	1	4.9	1	.6	1	0	.3	0	1	1	1	1	Good		6/28/2018	2	NO	Local
234	1	1	2.8	1	.7	1	1	1.4	0	1	1	1	1	Good		6/29/2018	1	NO	Local
235	1	1	4.0	1	.3	1	1	1.4	0	1	1	1	1	Good		6/29/2018	1	NO	Local
236	1	1	3.0	1	.1	1	1	1.7	0	1	1	1	1	Good		6/29/2018	1	NO	Local
237	1	1	3.0	1	1.1	1	1	1.7	0	1	1	1	1	Good		6/29/2018	1	NO	Local
238	1	1	3.4	1	.3	1	1	.3	0	1	1	1	1	Good		6/28/2018	1	NO	Local
239	1	1	6.3	1	1.0	1	1	0.3	1	1	1	1	1	Good		6/28/2018	0	YES	Local
240	1	1	6.7	1	0.7	1	1	1.8	1	1	1	1	1	Good		6/28/2018	0	YES	Local
241	1	1	3.0	1	.5	1	1	1.8	0	1	1	1	1	Good		6/28/2018	1	NO	Local
242	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
243	1	1	6.8	1	1.7	1	1	1.6	0	1	1	1	1	Good		6/29/2018	1	NO	Local
244	1	1	3.6	1	1.2	1	1	0.2	1	1	1	1	1	Good		6/29/2018	0	YES	Local
245	1	1	3.5	1	.8	1	1	.2	0	1	1	1	1	Good		6/29/2018	1	NO	Local
246	1	1	5.7	1	1.2	1	1	1.4	1	0	1	1	1	Good		6/28/2018	1	NO	Local
247	1	1	4.6	1	0.9	1	1	1.4	1	0	1	1	1	Good		6/28/2018	1	NO	Local
248	1	1	3.0	1	1.0	1	0	4.4	1	0	1	1	1	Good		6/28/2018	2	NO	Local
249	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
250	1	1	2.9	1	.5	1	1	1.4	0	1	1	1	1	Good		6/29/2018	1	NO	Local
251	1	1	3.4	1	.4	1	1	1.4	0	1	1	1	1	Good		6/29/2018	1	NO	Local
252	1	0	9.4	1	1.5	1	1	0.6	1	0	1	1	1	Good		6/28/2018	2	NO	Local
253	1	1	5.1	0	2.6	1	1	.6	0	0	1	1	1	Good		6/28/2018	3	NO	Local
254	1	1	4.2	1	0.3	1	1	0.6	1	0	1	1	1	Good		6/29/2018	1	NO	Local
255	1	1	4.1	1	0.3	1	1	0.6	1	0	1	1	1	Good		6/29/2018	1	NO	Local
256	1	1	4.3	1	1.2	1	1	1.5	0	1	1	1	1	Good		6/29/2018	1	NO	Local
257	1	1	4.9	1	2.0	1	1	1.5	1	1	1	1	0			6/29/2018	1	NO	Local
258	1	1	3.6	1	.7	1	1	1.1	0	1	1	1	1	Good		6/28/2018	1	NO	Local
259	1	1	3.2	1	1.4	1	1	1.1	0	1	1	1	1	Good		6/28/2018	1	NO	Local
260	1	1	3.6	1	.3	1	1	.5	0	0	1	1	1	Good		6/29/2018	2	NO	Local
261	1	1	5.0	1	1.6	1	1	.5	0	0	1	1	1	Good		6/29/2018	2	NO	Local
262	1	1	4.7	1	.9	1	1	.8	1	1	1	1	1	Good		6/29/2018	0	YES	Local
263	1	1	5.6	1	.9	1	1	.1	0	1	1	1	1	Good	gap by landing	6/28/2018	1	NO	Local
264	1	1	5.4	1	1.6	1	1	.8	0	0	1	1	1	Fair		6/29/2018	2	NO	Local
265	1	1	2.1	1	.8	1	0	2.8	0	0	0	0	1	Fair		6/29/2018	5	NO	Local
266	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
267	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
268	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
269	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
270	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
271	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
272	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
273	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
274	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
275	1	1	6.2	1	0.7	1	1	2.2	1	0	0	0	1	Fair	Vegetation growth along the back of curb.	6/29/2018	3	NO	Local
276	1	1	4.1	1	0.6	1	1	1.5	1	0	1	1	1	Good		6/29/2018	1	NO	Local
277	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
278	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
279	0	0		0		0	0		0	0	0	0	0		1.5" or greater gap	6/29/2018	10	NO	Local
280	1	1	5.4	1	2.0	1	1	1.5	1	0	1	1	1	Good		6/29/2018	1	NO	Local
281	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
282	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
283	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
284	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
285	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
286	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
287	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
288	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
289	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
290	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
291	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
292	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
293	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
294	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
295	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
296	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
298	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	Local
299	1	1	5.0	1	.3	1	0	3.3	0	0	1	1	1	Good		6/26/2018	3	NO	Local
300	1	0	11.9	1	.2	1	0	3.9	0	0	0	0	1	Fair	crack	6/26/2018	6	NO	Local
301	1	0	8.1	0	4.3	1	1	1.0	0	0	0	0	1	Fair		6/26/2018	6	NO	Local
302	1	1	7.8	1	.8	1	0	3.0	0	1	1	1	1	Good		6/26/2018	2	NO	Local
303	1	1	7.3	0	3.0	1	0	4.1	0	1	1	1	1	Good		6/26/2018	3	NO	Local
305	1	1	3.4	1	.3	1	1	1.8	0	0	0	0	1	Fair		6/29/2018	4	NO	Local
306	1	1	3.3	1	1.4	1	1	.5	0	1	1	1	1	Good		6/29/2018	1	NO	Local
307	1	1	1.6	1	.2	1	1	.8	1	1	1	1	1	Good		6/29/2018	0	YES	Local
308	1	1	1.7	1	.8	1	1	1.1	0	0	1	1	1	Good		6/29/2018	2	NO	Local
309	1	1	.9	1	.9	1	1	1.1	0	0	1	1	1	Good		6/29/2018	2	NO	Local
310	1	1	2.9	0	2.6	1	1	1.2	0	1	1	1	1	Good		6/29/2018	2	NO	Local
311	1	1	3.0	1	1.4	1	1	.7	0	1	1	1	1	Good		6/29/2018	1	NO	Local
312	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
313	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	State
314	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	State
315	1	1	3.6	1	.8	1	1	.5	1	1	1	1	1	Good		6/26/2018	0	YES	State
316	1	1	0.7	1	0.3	1	1	2.0	1	1	1	1	1	Good		6/26/2018	0	YES	State
317	1	1	2.7	1	1.1	1	1	1.4	1	1	1	1	1	Good		6/26/2018	0	YES	State
318	1	1	0.8	1	0.1	1	1	0.7	1	0	0	0	1	Good		6/26/2018	3	NO	State
319	1	1	.2	1	.3	1	1	1.2	1	0	1	1	1	Good	brick as sidewalk	6/26/2018	1	NO	State
320	1	1	0.3	1	0.3	1	1	0.7	1	0	1	1	1	Good		6/26/2018	1	NO	State
321	1	1	0.1	1	0.4	1	1	1.3	1	0	0	0	1	Good		6/26/2018	3	NO	State
322	1	1	3.4	1	0.2	1	1	0.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
323	1	1	3.8	1	0.2	1	1	1.1	1	1	1	1	1	Good		6/26/2018	0	YES	State
324	1	1	2.2	1	3.3	1	1	1.6	0	0	0	0	1	Fair	all brick	6/26/2018	4	NO	Local
325	1	1	4.3	1	1.9	1	1	.5	0	0	0	0	1	Fair	all brick	6/26/2018	4	NO	Local
326	1	1	5.2	1	.2	1	1	1.3	1	1	1	1	1	Good		6/26/2018	0	YES	State
327	1	1	8.3	1	0.2	1	1	1.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
329	1	1	4.7	1	1.1	1	1	.2	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
330	1	1	4.6	1	.3	1	1	1.2	0	0	0	0	1	Fair		6/26/2018	4	NO	Local
331	1	1	5.3	1	.2	1	1	.9	1	1	1	1	1	Good		6/26/2018	0	YES	Local
332	1	1	5.5	1	0.0	1	0	4.6	1	0	0	0	1	Fair		6/26/2018	4	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
333	1	1	1.9	1	.4	1	1	1.3	1	1	1	1	1	Good	water valve in landing	6/26/2018	0	YES	Local
334	1	1	3.7	1	.8	1	0	3.6	0	0	0	0	1	Fair		6/26/2018	5	NO	Local
335	1	1	2.5	1	.5	1	0	3.9	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
336	1	1	2.7	1	1.8	1	1	1.7	1	0	0	0	1	Fair	brick	6/26/2018	3	NO	Local
337	1	1	2.0	1	.5	1	1	1.3	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
338	1	1	4.0	1	0.2	0	1	1.6	1	0	0	0	1			6/26/2018	4	NO	Local
339	1	1	5.7	1	1.6	1	1	.4	1	0	0	0	1	Fair	no detect panels	6/25/2018	3	NO	Local
340	1	1	2.9%	1	.3	1	0	2.1%	1	1	1	1	1	Good		6/25/2018	1	NO	Local
341	1	1	5.0	1	.8	1	1	.5	0	0	0	0	1	Fair	no detect panels	6/25/2018	4	NO	Local
342	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
343	1	1	1.4	1	0.7	1	0		0	1	1	1	0			6/25/2018	3	NO	State
344	1	1	.7%	1	.7%	1	0	no landing	0	1	1	1	1	Good	proposed sidewalk no landing	6/25/2018	2	NO	State
345	1	0	8.7%	1	2.0%	1	1	1.4%	0	0	0	0	1	Fair	no detectible warning panels	6/25/2018	5	NO	Local
348	1	1	3.6%	1	.8%	1	0	2.1%	0	1	1	1	1	Fair		6/25/2018	2	NO	Local
349	1	1	4.0	0	2.2	1	1	.9	0	1	1	1	1	Good		6/28/2018	2	NO	Local
350	1	1	4.8	1	.8	1	0	3.1	0	1	1	1	1	Good		6/28/2018	2	NO	Local
351	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
352	1	1	2.6	1	.3	1	1	.7	0	1	1	1	1	Good	slight lip by landing	6/29/2018	1	NO	Local
353	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
354	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
355	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
356	1	1	3.5	1	0.1	1	1	1.2	1	0	0	0	1	Fair		6/28/2018	3	NO	Local
357	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
358	1	1	3.7	1	1.8	1	1	0.6	1	0	1	1	1	Good		6/29/2018	1	NO	Local
359	1	1	2.7	1	0.0	1	1	1.0	1	1	1	1	1	Good		6/29/2018	0	YES	Local
360	1	1	1.7	1	1.5	1	1	0.9	1	0	1	1	1	Good		6/29/2018	1	NO	Local
361	1	1	1.8	1	0.8	1	1	0.9	1	0	1	1	1	Good		6/29/2018	1	NO	Local
362	1	1	0.6	1	0.7	1	1	0.8	1	0	1	1	1	Good		6/29/2018	1	NO	Local
363	1	1	0.9	1	1.8	1	0	4.2	1	0	1	1	1	Good	Landing heaved up. Looks to be caused by heat.	6/29/2018	2	NO	Local
364	1	1	1.4	1	0.2	1	1	1.6	1	0	1	1	1	Good		6/29/2018	1	NO	Local
365	1	1	2.8	1	1.1	1	0	2.8	1	0	1	1	1	Good		6/29/2018	2	NO	Local
366	1	1	3.6	1	1.1	1	0	2.5	1	0	1	1	1	Good		6/29/2018	2	NO	Local
367	1	1	3.4	1	.7	1	1	2.1	0	0	1	1	1	Good		6/29/2018	2	NO	Local
368	1	1	2.3	1	1.4	1	1	.6	0	1	1	1	1	Good		6/29/2018	1	NO	Local
369	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
370	1	1	3.7	1	0.9	1	1	1.8	1	0	1	1	1	Good		6/29/2018	1	NO	Local
371	1	1	3.2	1	0.3	1	1	1.8	1	0	1	1	1	Good		6/29/2018	1	NO	Local
373	1	1	3.3	1	0.1	1	1	0.5	1	0	1	1	1	Good		6/29/2018	1	NO	Local
374	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
375	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
376	1	1	1.3	1	0.0	1	1	0.6	1	0	1	1	1	Good		6/29/2018	1	NO	Local
377	1	1	2.7	1	0.8	1	1	1.6	1	1	1	1	1	Good		6/29/2018	0	YES	Local
378	1	1	5.1	1	0.6	1	1	1.6	1	1	1	1	1	Good		6/29/2018	0	YES	Local
379	1	1	2.9	1	.7	1	1	1.8	0	1	1	1	1	Good		6/29/2018	1	NO	Local
380	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
381	1	1	3.0	1	0.7	1	1	2.0	1	1	1	1	1	Good		6/29/2018	0	YES	Local
382	1	1	2.7	1	0.1	1	1	2.0	1	1	1	1	1	Good		6/29/2018	0	YES	Local
383	1	1	3.1	1	.1	1	1	1.8	0	1	1	1	1	Good		6/29/2018	1	NO	Local
384	1	1	2.9	1	.4	1	1	1.8	0	1	1	1	1	Good		6/29/2018	1	NO	Local
385	1	1	2.0	1	1.2	0	1	1.0	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
386	1	1	3.9	1	.1	0	1	1.0	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
387	1	1	3.3	1	1.4	1	1	1.5	0	0	1	1	1	Good		6/29/2018	2	NO	Local
389	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
390	1	1	1.2	1	.4	1	1	1.5	0	0	0	0	1	Fair		6/29/2018	4	NO	Local
391	1	1	1.3	1	.3	1	1	1.5	0	0	1	1	1	Good		6/29/2018	2	NO	Local
392	1	1	1.5	1	.2	1	1	1.7	0	1	1	1	1	Good		6/29/2018	1	NO	Local
393	1	1	7.4	1	.5	1	1	1.7	1	0	0	0	1	Fair		6/29/2018	3	NO	Local
394	1	1	3.2	1	0.1	1	1	1.6	1	1	1	1	1	Good		6/29/2018	0	YES	Local
395	1	1	3.8	1	.8	1	1	1.5	0	0	0	0	1	Fair		6/29/2018	4	NO	Local
396	1	1	3.0	1	.3	1	1	1.5	0	1	1	1	1	Good		6/29/2018	1	NO	Local
397	1	1	4.3	1	.2	1	1	1.3	1	1	1	1	1	Good		6/29/2018	0	YES	Local
398	1	1	6.1	1	1.0	1	0	2.3	0	0	0	0	1	Fair		6/29/2018	5	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
399	1	1	3.3	1	0.5	1	1	0.7	1	0	0	0	0	Fair	1.5" or greater gap near the landing	6/29/2018	4	NO	Local
400	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
401	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
402	1	1	6.4	1	0.3	0	1	1.7	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
403	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
404	1	1	4.2	1	0.6	1	1	1.4	1	1	1	1	1	Good		6/29/2018	0	YES	Local
405	1	1	2.5	1	.8	1	1	1.1	1	1	1	1	1	Good		6/29/2018	0	YES	Local
406	1	1	2.2	1	0.5	1	1	1.1	1	0	1	1	1	Good		6/29/2018	1	NO	Local
407	1	1	1.4	1	0.7	1	1	2.0	1	0	0	0	1	Fair		6/29/2018	3	NO	Local
408	1	1	0.6	1	0.4	1	1	2.0	1	0	1	0	1	Fair		6/29/2018	2	NO	Local
409	1	1	0.2	1	0.4	1	0	2.8	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
410	1	1	2.6	1	1.0	1	0	2.8	1	0	0	0	0	Fair		6/29/2018	5	NO	Local
411	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
412	1	1	5.1	1	0.7	1	1	1.5	1	0	0	0	1	Fair		6/29/2018	3	NO	Local
413	1	1	4.4	1	1.1	1	1	2.0	1	0	1	1	1	Good		6/29/2018	1	NO	Local
414	1	1	1.8	1	0.4	1	1	2.0	1	0	1	1	1	Good		6/29/2018	1	NO	Local
415	1	1	1.9	1	0.6	1	1	0.8	1	0	1	1	1	Good		6/29/2018	1	NO	Local
416	1	1	3.8	1	0.2	1	1	0.8	1	0	1	1	1	Good		6/29/2018	1	NO	Local
417	1	1	3.8	1	0.2	1	1	0.3	1	0	1	1	1	Good		6/29/2018	1	NO	Local
418	1	1	2.8	1	0.7	1	1	0.3	1	0	1	1	0	Good		6/29/2018	2	NO	Local
419	1	1	4.3	1	0.8	1	1	1.4	1	0	1	1	1	Good		6/29/2018	1	NO	Local
420	1	1	2.3	1	0.9	1	1	1.4	1	0	1	1	1	Good		6/29/2018	1	NO	Local
421	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
422	1	1	1.1	1	0.4	1	1	2.0	1	0	1	1	1	Good		6/29/2018	1	NO	Local
423	1	1	2.9	1	0.5	1	1	0.5	1	0	1	1	1	Good		6/29/2018	1	NO	Local
424	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
425	1	1	2.3	1	.2	1	1	.8	0	1	1	1	1	Good		6/29/2018	1	NO	Local
426	1	1	1.8	1	.5	1	1	.8	0	1	1	1	1	Good		6/29/2018	1	NO	Local
427	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
428	1	1	1.9	1	.3	1	1	.6	1	1	1	1	1	Good		6/29/2018	0	YES	Local
429	1	1	2.1	1	1.5	1	0	2.2	0	0	1	1	1	Good		6/29/2018	3	NO	Local
430	1	1	.1	1	.3	1	0	2.2	0	0	1	1	1	Good		6/29/2018	3	NO	Local
431	1	1	2.6	1	.8	1	1	1.4	0	0	1	1	1	Good		6/29/2018	2	NO	Local
432	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
433	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
434	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
435	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
436	1	1	4.6	1	1.2	0	0	no landing	1	0	0	0	1	Fair	doesnt tie into sidewalk	6/29/2018	5	NO	Local
437	1	1	6.3	1	.5	0	1	1.3	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
438	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
439	1	1	6.2	1	.7	0	1	.7	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
440	1	1	3.4	1	.5	1	1	1.3	1	1	1	1	1	Good		6/29/2018	0	YES	Local
441	1	1	2.0	1	.5	1	1	1.3	0	1	1	1	1	Good	water gate valve in sidewalk	6/29/2018	1	NO	Local
444	1	1	4.8	1	0.7	1	1	1.4	1	1	1	1	0	Good	Water gate valve sticking up through the sidewalk.	6/29/2018	1	NO	Local
445	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
446	1	1	2.9	1	.6	1	1	1.6	0	0	1	1	1	Good		6/29/2018	2	NO	Local
448	1	1	3.9	1	.4	1	1	1.0	0	1	1	1	1	Good		6/29/2018	1	NO	Local
449	1	1	1.9	1	.4	1	1	1.8	0	0	1	1	1	Fair		6/29/2018	2	NO	Local
450	1	1	1.6	1	.6	1	1	1.8	0	0	1	1	1	Good		6/29/2018	2	NO	Local
452	1	1	4.2	1	.3	1	1	1.5	1	0	1	1	1	Good		6/29/2018	1	NO	Local
453	1	1	2.0	1	.1	1	1	1.5	0	0	1	1	1	Good		6/29/2018	2	NO	Local
454	1	1	1.5	1	.2	1	1	1.1	0	0	1	1	1	Good		6/29/2018	2	NO	Local
455	1	1	4.1	1	0.0	1	1	1.1	0	0	1	1	1	Good		6/29/2018	2	NO	Local
456	1	1	3.6	1	.2	1	1	.5	1	1	1	1	1	Good		6/29/2018	0	YES	Local
457	1	1	2.7	1	0.0	1	1	.4	0	1	1	1	1	Good		6/29/2018	1	NO	Local
458	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
459	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
460	1	1	4.0	1	.4	1	1	.7	0	1	1	1	1	Good		6/29/2018	1	NO	Local
461	1	1	5.2	1	.7	1	1	.5	0	1	1	1	1	Good		6/29/2018	1	NO	Local
462	1	1	3.5	1	.7	1	1	.5	0	1	1	1	1	Good		6/29/2018	1	NO	Local
463	1	1	1.6	1	.4	1	1	1.8	0	0	0	0	1	Fair		6/29/2018	4	NO	Local
464	1	1	.9	1	.5	1	1	1.8	0	0	0	0	1	Fair		6/29/2018	4	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
465	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
466	0	0		0		0	0		0	0	0	0	0			6/29/2018	10	NO	Local
467	1	1	5.3	1	1.6	1	1	.1	1	1	1	1	1	Good		6/29/2018	0	YES	Local
469	1	1	1.3	1	.8	1	1	1.6	0	0	0	0	1	Fair		6/29/2018	4	NO	Local
472	1	1	1.0	1	.8	1	1	.6	1	1	1	1	1	Good		6/29/2018	0	YES	Local
473	1	1	5.7	1	.5	1	0	2.4	0	0	0	0	1	Fair		6/29/2018	5	NO	Local
477	1	1	5.3	1	.3	1	1	.3	1	1	1	1	1	Good		6/29/2018	0	YES	Local
478	1	1	7.0	1	.5	1	1	.9	1	1	1	1	1	Good		6/29/2018	0	YES	Local
479	1	1	4.8	1	1.3	1	1	.5	1	1	1	1	1	Good		6/29/2018	0	YES	Local
480	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
481	1	1	4.5	1	.4	1	1	1.5	1	1	1	1	1	Good		6/29/2018	0	YES	Local
482	1	1	5.0	1	0.1	1	0	2.1	1	0	1	1	1	Good		6/29/2018	2	NO	Local
483	1	1	4.3	1	0.0	1	1	.7	1	1	1	1	1	Good		6/29/2018	0	YES	Local
484	1	1	3.4	1	.1	1	1	.4	1	1	1	1	1	Good		6/29/2018	0	YES	Local
485	1	1	5.1	1	1.1	1	1	.4	1	1	1	1	1	Good		6/29/2018	0	YES	Local
486	1	1	4.7	1	0.1	1	1	0.4	1	0	1	1	1	Good		6/29/2018	1	NO	Local
487	1	1	4.3	1	0.5	1	1	0.3	1	0	1	1	1	Good		6/29/2018	1	NO	Local
488	1	1	4.4	1	1.2	1	0	2.8	1	0	1	1	1	Good		6/29/2018	2	NO	Local
489	1	1	4.0%	1	.5%	1	1	.9%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
490	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
493	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
494	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
495	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
496	1	1	2.1%	1	.8%	1	1	1.2%	1	0	0	0	0	Fair	no detect warning panels	6/25/2018	4	NO	Local
497	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
498	1	1	1.7%	0	3.1%	0	1	.5%	0	0	0	0	1	Fair	no detect panels, not full width	6/25/2018	6	NO	Local
499	1	1	4.4%	1	.7%	1	1	.2%	1	0	0	0	1	Fair	no detectible warning panels	6/25/2018	3	NO	Local
500	1	1	3.1%	1	.5%	1	1	.2%	0	0	0	0	1	Fair		6/25/2018	4	NO	Local
501	1	1	2.4%	1	1.7%	1	1	1.2%	1	0	0	0	1	Fair	no detect warning panels	6/25/2018	3	NO	Local
502	1	1	5.6%	1	.8	1	1	1.6%	0	0	0	0	1	Fair	no detect panels, grass	6/25/2018	4	NO	Local
503	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
504	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
505	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
506	0	0		0		0	0		0	0	0	0	0		major gap from curb to sidewalk	6/25/2018	10	NO	Local
507	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
508	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
509	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
510	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
511	1	1	3.1%	1	.4%	1	0	2.2% ns dir	0	0	0	0	0	Fair	1.5" gap on landing, no detectible warning panels	6/25/2018	6	NO	Local
512	1	1	2.9%	1	.7%	1	1	1.9%	0	0	0	0	0	Fair	no detectable warning panels or flares	6/25/2018	5	NO	Local
513	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
514	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
515	1	1	2.8%	1	.5%	0	1	.7%	0	0	0	0	0	Fair	growth of grass into ramp are	6/25/2018	6	NO	Local
516	1	1	4.3%	1	1.9%	1	1	1.7%	0	0	0	0	0	Fair	no truncated domes of flares	6/25/2018	5	NO	Local
517	1	1	3.2%	1	1.3%	1	1	.4%	0	0	0	0	0	Fair	no detectible warning panels or flares	6/25/2018	5	NO	Local
518	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
519	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
520	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
521	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
522	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
523	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
524	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
525	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
526	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
527	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
528	1	1	5.2%	1	1.1%	1	1	1.2%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
529	1	1	4.1	1	0.8	1	1	1.2	0	1	1	1	0	Good		6/25/2018	2	NO	Local
530	1	1	5.5%	1	1.7%	1	0	2.2%	0	1	1	1	0	Fair	grass in sidewalks	6/25/2018	3	NO	Local
531	1	1	4.2	1	0.2	1	0	2.2	0	1	1	1	0	Good		6/25/2018	3	NO	Local
532	1	1	2.0%	1	.3%	1	1	1.5%	0	0	0	0	1	Fair	no detectible panels	6/25/2018	4	NO	Local
533	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
534	1	1	2.9%	1	.9%	1	1	.7%	0	0	0	0	1	Fair	no detectible panel	6/25/2018	4	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
535	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
536	1	1	3.2	1	0.2	1	1	0.3	0	1	1	1	1	Good		6/25/2018	1	NO	Local
537	1	1	3.6%	1	.1%	0	0	.3%	0	0	0	0	1	Fair	no detect panela	6/25/2018	6	NO	Local
538	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
539	1	1	3.1%	1	.3%	1	1	.6%	1	0	0	0	1	Fair	wearing at the landing and a slight gap after landing	6/25/2018	3	NO	Local
540	0	0		0		0	0		0	0	0	0	0		Bus Stop Route 11	6/25/2018	10	NO	Local
541	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
542	1	1	5.4	1	0.2	1	0	2.3	0	0	0	0	1	Fair		6/25/2018	5	NO	Local
543	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
544	1	1	3.3	1	.1	1	1	.6	0	0	0	0	1	Fair	no det panel, cracking in landing	6/25/2018	4	NO	Local
545	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
546	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
547	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
548	1	1	3.9%	1	.4%	1	1	1.1%	1	1	1	1	1	Good		6/25/2018	0	YES	State
549	1	1	1.3%	1	.8%	1	1	.9%	0	1	1	1	1	Good		6/25/2018	1	NO	State
551	1	1	3.1%	1	.4%	1	1	.7%	1	1	1	1	0	Good		6/25/2018	1	NO	State
552	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
555	1	1	0.3	1	0.5	1	1	0.5	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
556	1	1	0.8	1	0.8	1	1	0.8	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
557	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
558	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
559	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
560	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
561	1	1	2.8	1	0.5	0	1	1.3	0	1	1	1	1	Good		6/25/2018	2	NO	Local
562	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
563	1	1	3.3	1	0.0	1	1	0.8	0	1	1	1	1	Good		6/27/2018	1	NO	Local
564	1	1	3.8	1	0.3	1	1	0.8	0	1	1	1	0	Good		6/25/2018	2	NO	Local
565	0	0		0		0	0		0	0	0	0	0		Tree overhang on sidewalk.	6/25/2018	10	NO	Local
566	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
567	1	1	1.9%	1	.2%	1	1	.8%	0	0	0	0	1	Fair	no detect panels	6/25/2018	4	NO	Local
568	1	1	1.4%	1	.5%	1	1	.6%	0	0	0	0	1	Fair	no detect panels	6/25/2018	4	NO	Local
569	1	1	2.6%	1	.8%	1	1	1.1%	1	0	0	0	1	Fair	no detect panels	6/25/2018	3	NO	Local
570	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
571	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
572	1	1	6.5	1	1.0	0	0	1.1	0	0	0	0	1	Fair		6/25/2018	6	NO	Local
573	1	1	5.2%	1	1.2%	1	0	1.3%	0	0	0	0	1	Fair	no detect panels	6/25/2018	5	NO	Local
574	1	1	3.8	1	.4	1	1	2.0	0	1	1	1	1	Good		6/25/2018	1	NO	Local
575	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
576	1	1	3.6	1	0	1	1	2.0	1	1	1	1	1	Good		6/25/2018	0	YES	Local
577	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
578	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
579	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
580	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
581	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
582	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
583	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
584	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
585	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
586	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
587	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
588	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
589	1	1	4.3%	1	.3%	1	0	2.9%	0	0	0	0	1	Fair	no detect panels	6/25/2018	5	NO	Local
590	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
591	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
592	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
593	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
594	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
595	1	1	3.8%	1	.8%	1	1	.8%	0	0	0	0	0	Fair	about 1.25" gap no detect panels	6/25/2018	5	NO	Local
596	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
597	1	1	2.6%	1	.5%	1	1	.6%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
598	1	1	2.8%	1	.5%	1	1	.6%	1	1	1	1	1	Good		6/25/2018	0	YES	Local
599	1	1	4.6%	1	.8%	1	1	1.0%	1	1	1	1	1	Good	new ramps	6/25/2018	0	YES	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
600	1	1	3.8%	1	.3%	1	1	1.0%	0	1	1	1	0	Good		6/25/2018	2	NO	Local
601	1	1	2.8%	1	1.8	1	1	1.4	1	1	1	1	1	Good		6/25/2018	0	YES	Local
602	1	1	3.9	1	.3	1	1	1.4	1	1	1	1	1	Good		6/25/2018	0	YES	Local
603	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
604	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
605	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
606	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
607	1	1	4.2	1	.4	1	1	2.0	0	1	1	1	1	Good		6/25/2018	1	NO	Local
608	1	1	1.8	1	0.1	1	1	2.0	0	1	1	1	0	Good		6/25/2018	2	NO	Local
609	1	1	1.9	1	0.2	1	1	1.3	0	1	1	1	1	Good		6/25/2018	1	NO	Local
610	1	1	2.6%	1	.5%	1	1	1.3%	1	1	1	1	1	Good		6/25/2018	0	YES	Local
611	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
612	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
613	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
614	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
615	1	1	2.4	1	1.1	1	1	1.1	0	1	1	1	1	Good		6/25/2018	1	NO	Local
616	1	1	2.0	1	0.0	1	1	1.1	0	1	1	1	0	Good		6/25/2018	2	NO	Local
617	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
618	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
619	1	1	2.9%	1	.3%	1	1	.9%	1	1	1	1	1	Good		6/25/2018	0	YES	Local
620	1	1	3.0%	1	.3%	1	1	.9%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
621	1	1	4.1%	1	.3%	1	1	1.0%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
622	1	1	4.6%	1	.2%	1	1	1.0%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
623	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
624	1	1	1.8	1	0.1	1	1	1.6	0	0	0	0	1	Fair		6/25/2018	4	NO	Local
625	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
626	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
627	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
628	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
629	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
630	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
631	1	1	6.4%	1	.7%	1	1	.8%	0	0	0	0	1	Fair	no detect panels	6/25/2018	4	NO	Local
632	1	1	5.4%	1	.5%	1	1	.9%	0	0	0	0	1	Fair	no detect panels	6/25/2018	4	NO	Local
633	1	1	.7%	1	.3%	1	1	.6%	1	1	1	1	1	Good		6/25/2018	0	YES	State
634	1	1	1.2	1	0.5	1	0	0.6	0	1	1	1	1	Good		6/25/2018	2	NO	State
635	1	1	1.2	1	0.7	1	1	0.9	0	1	1	1	1	Good		6/25/2018	1	NO	State
636	1	1	2.5%	1	.4%	1	1	.9%	1	1	1	1	1	Good		6/25/2018	0	YES	State
637	1	1	.1%	1	.7%	1	0	no landing	1	1	1	1	1	Good	proposed sidewalk	6/25/2018	1	NO	State
638	1	1	0.7	1	0.7	0	0		0	1	1	1	1	Good		6/25/2018	3	NO	State
639	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	State
640	1	1	4.5%	1	.8%	1	1	.7%	1	1	1	1	1	Good		6/25/2018	0	YES	State
641	1	1	4.6%	1	.1%	1	1	.8%	1	1	1	1	1	Good		6/25/2018	0	YES	State
642	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	State
643	1	1	2.6	1	0.5	1	1	0.8	0	1	1	1	1	Good		6/25/2018	1	NO	Local
644	1	1	3.5	1	.4	1	1	.8	0	1	1	1	1	Good		6/25/2018	1	NO	Local
645	1	1	2.7%	1	.2%	0	1	.7%	1	1	1	1	1	Good		6/25/2018	1	NO	Local
646	1	1	4.2%	1	.5%	1	1	.7%	1	1	1	1	1	Good		6/25/2018	0	YES	Local
647	1	1	1.8	1	.9	1	1	1.2	1	0	1	1	1	Good		6/25/2018	1	NO	Local
648	1	1	6.2	1	1.0	1	1	0.6	0	0	0	0	0	Fair	Vegetation growth on bottom of curb ramp.	6/25/2018	5	NO	Local
649	1	1	4.0	1	1.2	1	1	0.7	0	0	0	0	1	Fair		6/25/2018	4	NO	Local
650	1	1	2.3	0	3.7	0	0	2.5	0	0	0	0	1	Fair	no detect panels	6/25/2018	7	NO	Local
651	1	1	4.6	0	1.8	0	0	2.5	0	0	0	0	1	Fair	no det panels	6/25/2018	7	NO	Local
652	1	1	3.5	1	0.5	1	1	0.9	0	1	1	1	1	Good		6/25/2018	1	NO	Local
653	1	1	4.5%	1	.1%	1	1	.9%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
655	1	1	3.0	1	1.0	1	1	1.4	0	1	1	1	1	Good		6/25/2018	1	NO	Local
656	1	1	1.9	1	.6	1	1	.3	0	1	1	1	1	Good		6/25/2018	1	NO	Local
657	1	1	2.3	1	.1	1	1	.3	1	1	1	1	1	Good		6/25/2018	0	YES	Local
658	1	1	2.9	1	0.4	1	1	0.8	0	1	1	1	1	Good		6/25/2018	1	NO	Local
659	1	1	2.7	1	0.2	1	1	0.8	0	1	1	1	1	Good		6/25/2018	1	NO	Local
660	1	1	2.7	1	0.6	1	1	1.4	0	1	1	1	1	Good		6/25/2018	1	NO	Local
661	1	1	2.1	1	.4	1	1	1.4	0	1	1	1	1	Good		6/25/2018	1	NO	Local
662	1	1	2.6	1	0.0	1	1	0.7	0	1	1	1	1	Good		6/25/2018	1	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
663	1	1	2.4	1	0.3	1	1	0.7	0	1	1	1	0	Good		6/25/2018	2	NO	Local
664	1	1	6.8	1	.5	0	1	.6	0	0	0	0	1	Fair		6/25/2018	5	NO	Local
665	1	1	7.3	1	.3	1	0	2.3	0	0	0	0	1	Poor	gap, curb by edge is cracked	6/25/2018	5	NO	Local
666	1	1	1.9	1	0.6	1	0	2.3	0	0	0	0	1	Fair		6/25/2018	5	NO	Local
667	1	1	2.3	1	1.6	0	1	1.1	1	0	0	0	1	Fair	no detect panels	6/25/2018	4	NO	Local
668	1	1	4.8	1	2.2	0	0	2.1	1	0	0	0	1	Fair		6/26/2018	5	NO	Local
669	1	1	7.2	1	1.4	0	1	1.0	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
670	1	1	8.2	1	.6	1	0	3.5	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
671	1	1	4.8	0	2.1	1	1	.6	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
672	0	0		0		0	0		0	0	0	0	0			6/25/2018	10	NO	Local
674	1	1	5.5	1	.6	1	1	1.1	1	0	0	0	1	Fair	no detect panels	6/25/2018	3	NO	Local
675	1	1	4.0	1	.7	1	1	.5	0	0	0	0	0	Fair		6/26/2018	5	NO	Local
676	1	1	4.9	1	1.5	1	1	1.3	0	0	0	0	1	Fair	no detect panels	6/25/2018	4	NO	Local
677	1	1	3.7	1	1.6	0	1	1.3	0	0	0	0	1	Fair	bad spot in concrete	6/25/2018	5	NO	Local
678	1	1	1.2	1	0.1	1	1	0.3	0	0	0	0	0	Fair		6/25/2018	5	NO	Local
679	1	1	4.5	1	1.1	1	1	.3	0	0	0	0	1	Fair		6/25/2018	4	NO	Local
680	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	Local
681	1	1	3.9	1	.3	1	1	1.4	1	1	1	1	1	Good		6/25/2018	0	YES	Local
682	1	1	4.2	1	.4	1	1	1.4	0	1	1	1	1	Good		6/25/2018	1	NO	Local
683	1	1	4.5	1	0.9	1	1	0.9	0	0	1	1	1	Good		6/25/2018	2	NO	Local
684	1	1	4.0	1	0.6	1	1	0.9	0	0	1	1	1	Good		6/25/2018	2	NO	Local
685	1	1	2.7	1	1.1	1	1	1.0	1	1	1	1	1	Good		6/25/2018	0	YES	Local
686	1	1	3.8	1	.9	1	1	1.0	0	1	1	1	1	Good		6/25/2018	1	NO	Local
687	1	1	4.0	1	0.5	1	1	0.7	0	0	1	1	1	Good		6/25/2018	2	NO	Local
688	1	1	2.9	1	0.2	1	1	0.7	0	1	1	1	1	Good		6/25/2018	1	NO	Local
689	1	1	4.2	1	.3	1	1	.7	0	1	1	1	1	Good		6/25/2018	1	NO	Local
690	1	1	2.4	1	0.7	1	1	0.7	0	1	1	1	1	Good		6/25/2018	1	NO	Local
691	1	1	3.6	1	.3	0	0	.6	0	0	0	0	0	Poor		6/26/2018	7	NO	Local
692	1	1	4.1	1	.9	1	1	1.5	0	0	0	0	1	Fair	no detect panels	6/25/2018	4	NO	Local
693	1	1	4.2	1	1.5	1	1	1.5	0	0	0	0	1	Good		6/25/2018	4	NO	Local
694	1	1	4.2	1	.7	1	1	1.3	0	0	0	0	1	Fair	slight gap	6/25/2018	4	NO	Local
695	1	1	5.8	1	.2	1	1	1.3	0	0	0	0	1	Fair		6/25/2018	4	NO	Local
696	1	1	0.9	1	0.1	1	1	1.1	0	0	1	1	1	Good		6/25/2018	2	NO	Local
697	1	1	5.6	1	0.6	1	1	1.1	0	0	1	1	1	Good		6/25/2018	2	NO	Local
698	1	1	2.7	1	0.1	1	1	0.7	0	1	1	1	1	Good		6/25/2018	1	NO	Local
699	1	1	2.9	1	.1	1	1	.7	1	1	1	1	1	Good		6/25/2018	0	YES	Local
700	1	1	1.8	1	0.8	1	1	1.2	0	0	1	1	0	Good		6/25/2018	3	NO	Local
701	1	1	2.5	1	0.7	1	1	1.2	0	0	1	1	1	Good		6/25/2018	2	NO	Local
702	1	1	1.5%	1	1.4	1	0	2.8	0	0	0	0	1	Fair	no detect panels	6/25/2018	5	NO	Local
703	1	1	3.4	1	0.2	1	0	2.8	0	0	0	0	1	Fair		6/25/2018	5	NO	Local
704	1	1	7.7	1	1.1	1	1	2.0	0	1	1	1	1	Good		6/25/2018	1	NO	Local
705	1	1	4.1%	1	1.1	1	1	1.2%	0	0	0	0	1	Fair	no detect panel	6/25/2018	4	NO	Local
706	1	1	4.7	1	1.1	1	1	0.9	0	1	1	1	1	Good		6/25/2018	1	NO	Local
707	1	1	3.3	1	0.2	1	1	0.9	0	1	1	1	1	Good		6/25/2018	1	NO	Local
708	1	1	3.5	1	0.4	1	1	0.9	0	1	1	1	0	Good		6/25/2018	2	NO	Local
709	1	1	3.8	1	1.3	1	1	0.9	0	1	1	1	1	Good		6/25/2018	1	NO	Local
710	1	1	5.4%	1	1.8%	1	0	4.2%	1	0	1	1	1	Fair	some grass	6/25/2018	2	NO	Local
711	1	1	2.6%	0	3.0%	1	0	4.2%	0	1	1	1	1	Fair		6/25/2018	3	NO	Local
712	1	1	4.2%	1	.5%	0	0	no landing	1	1	1	1	1	Good		6/25/2018	2	NO	Local
713	1	1	4.2	1	0	1	1	.5	1	1	1	1	1	Good		6/26/2018	0	YES	State
714	1	1	2.2	1	0.8	1	1	.5	1	1	1	1	1	Good		6/26/2018	0	YES	State
715	1	1	3.7	1	.3	1	1	1.2	1	1	1	1	1	Good		6/26/2018	0	YES	State
716	1	1	3.6	1	.1	1	1	1.2	1	1	1	1	1	Good		6/26/2018	0	YES	State
717	1	1	3.4	1	1.1	1	1	1.2	1	1	1	1	1	Good		6/26/2018	0	YES	State
718	1	1	1.0	1	.3	1	1	1.2	0	1	1	1	1	Good		6/26/2018	1	NO	State
719	1	1	3.6	1	.7	1	1	.9	1	1	1	1	1	Good		6/26/2018	0	YES	State
720	1	1	4.8	1	.7	1	1	1.4	1	1	1	1	1	Good		6/26/2018	0	YES	State
721	1	1	3.1	1	1.5	1	0	3.5	1	0	1	1	1	Fair		6/26/2018	2	NO	Local
722	1	1	5.1	1	.1	1	0	3.5	1	1	1	1	1	Fair		6/26/2018	1	NO	Local
723	1	1	2.2	0	2.1	1	1	3.1	0	1	1	1	1	Good		6/25/2018	2	NO	Local
724	1	1	4.0	1	1.2	1	0	3.1	0	1	1	1	1	Good		6/25/2018	2	NO	Local
725	1	1	4.1	1	0.3	1	1	1.7	0	0	1	1	1	Good		6/26/2018	2	NO	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
726	1	1	3.9	1	0.0	1	1	1.7	0	0	1	1	1	Good		6/26/2018	2	NO	Local
727	1	1	2.1	1	0.3	1	0	2.5	1	0	1	1	1	Good		6/26/2018	2	NO	Local
728	1	1	6.1	0	2.7	1	0	2.5	1	0	1	1	0	Good		6/26/2018	4	NO	Local
729	1	1	2.8	1	0.7	1	1	1.5	1	0	0	0	0	Fair	1.5" or greater gap between curb ramp and back of curb.	6/26/2018	4	NO	Local
730	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	Local
731	1	1	3.4	1	0.0	1	0	2.8	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
732	1	1	3.4	1	.2	1	0	2.8	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
733	1	1	4.0	1	2.0	1	0	2.8	0	0	0	0	1	Fair		6/26/2018	5	NO	Local
734	1	1	4.5	1	.3	1	0	2.8	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
735	1	1	5.6	1	1.5	1	0	2.8	0	0	0	0	1	Fair		6/26/2018	5	NO	Local
736	0	0		0		0	0		0	0	0	0	0			6/26/2018	10	NO	Local
737	1	1	1.2	1	.3	1	1	.7	1	1	1	1	1	Good		6/26/2018	0	YES	State
738	1	1	3.1	1	.2	1	1	.7	1	1	1	1	1	Good		6/26/2018	0	YES	State
739	1	1	1.9	1	.6	1	1	1.2	0	1	1	1	1	Good		6/26/2018	1	NO	State
740	1	1	3.9	1	.7	1	1	1.2	0	1	1	1	1	Good		6/26/2018	1	NO	State
741	1	1	1.8	1	.2	1	1	1.0	1	1	1	1	1	Good		6/26/2018	0	YES	State
742	1	1	1.5	1	.5	1	1	1.0	0	1	1	1	1	Good		6/26/2018	1	NO	State
743	1	1	2.3	1	.3	1	1	1.0	1	1	1	1	1	Good		6/26/2018	0	YES	State
744	1	1	2.0	1	.4	1	1	1.0	1	1	1	1	1	Good		6/26/2018	0	YES	State
745	1	1	5.2	1	.2	1	0	2.4	1	0	0	0	1	Fair	small gap between ramp and sidewalk, grass	6/26/2018	4	NO	Local
746	1	1	5.3	1	2.0	1	0	2.4	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
747	1	0	9.1	1	1.9	0	1	1.0	1	0	0	0	1	Poor		6/26/2018	5	NO	Local
748	1	1	8.1	1	1.3	1	1	1.0	1	0	0	0	1	Poor	Vegetation growth in the cracks of the curb ramp.	6/26/2018	3	NO	Local
749	1	1	6.9	1	1.4	1	1	2.0	0	0	0	0	1	Fair		6/26/2018	4	NO	Local
750	1	1	9.0	1	2.0	1	1	2.0	0	0	0	0	1	Fair	no det panels	6/26/2018	4	NO	Local
751	1	1	6.3	1	.7	1	0	2.2	0	0	0	0	1	Fair		6/26/2018	5	NO	Local
752	1	1	5.8	1	1.2	1	0	2.2	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
753	1	1	4.0	1	.5	1	1	.7	1	1	1	1	1	Good		6/26/2018	0	YES	State
754	1	1	2.9	1	.1	1	1	.7	1	1	1	1	1	Good		6/26/2018	0	YES	State
755	1	1	3.3	1	.2	1	1	.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
756	1	1	4.6	1	0.2	1	1	0.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
757	1	1	0.5	1	0.9	1	1	1.1	1	1	1	1	1	Good		6/26/2018	0	YES	State
758	1	1	2.4	1	0.4	1	1	0.5	1	1	1	1	1	Good		6/26/2018	0	YES	State
759	1	1	3.0	1	0.3	1	1	0.5	1	1	1	1	0	Good		6/26/2018	1	NO	State
760	1	1	2.3	1	.5	1	1	1.0	0	1	1	1	1	Good		6/26/2018	1	NO	State
761	1	1	3.5	1	.4	1	1	1.0	1	1	1	1	1	Good		6/26/2018	0	YES	State
762	1	1	2.9	1	1.2	1	1	1.2	1	1	1	1	1	Good		6/26/2018	0	YES	State
763	1	1	4.2	1	0.5	1	1	1.2	1	1	1	1	1	Good		6/26/2018	0	YES	State
764	1	1	0.8	1	0.2	1	1	0.7	1	1	1	1	1	Good		6/26/2018	0	YES	State
765	1	1	0.7	1	0.1	1	1	0.7	1	1	1	1	1	Good		6/26/2018	0	YES	State
766	1	1	4.5	1	.9	1	1	1.3	1	1	1	1	1	Good		6/26/2018	0	YES	State
767	1	1	2.7	1	1.2	1	1	1.3	1	1	1	1	1	Good		6/26/2018	0	YES	State
768	1	1	5.8	1	0.5	0	1	1.2	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
769	1	1	3.8%	1	.4%	1	1	.8%	1	1	1	1	1	Good		6/25/2018	0	YES	State
770	1	1	5.4	1	1.8	1	1	0.8	0	0	0	0	0	Fair		6/25/2018	5	NO	Local
771	1	1	2.9	0	2.1	1	1	1.0	0	0	0	0	0	Fair		6/25/2018	6	NO	Local
772	1	1	1.8%	1	.5%	1	1	1.8%	0	0	0	0	1	Fair	no detect panels	6/25/2018	4	NO	Local
773	1	1	2.2%	1	1.2%	1	1	.6%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
774	1	1	4.2	1	1.3	1	1	0.8	0	1	1	1	0	Good		6/25/2018	2	NO	Local
775	1	1	1.5%	1	.6%	1	1	.8%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
776	1	1	2.0%	1	2.0%	1	1	1.2%	0	1	1	1	1	Good		6/25/2018	1	NO	Local
777	1	1	0.3	1	1.2	1	1	0.6	0	1	1	1	1	Good		6/25/2018	1	NO	Local
778	1	1	1.2%	1	1.8%	1	1	.8	1	1	1	1	1	Good		6/25/2018	0	YES	Local
779	1	1	1.9	1	0.2	1	1	1.6	0	1	1	1	1	Good		6/25/2018	1	NO	Local
780	1	1	1.5	1	1.1	1	1	1.6	0	1	1	1	1	Good		6/25/2018	1	NO	Local
782	1	1	.5%	1	.8%	1	1	1.9	0	1	1	1	1	Good		6/25/2018	1	NO	Local
783	1	1	4.0	1	1.6	1	1	1.1	0	1	1	1	1	Good		6/25/2018	1	NO	Local
784	1	1	2.3%	1	.2%	1	1	.9	0	1	1	1	1	Good		6/25/2018	1	NO	Local
785	1	1	1.8	1	0.5	1	1	1.9	0	1	1	1	1	Good		6/25/2018	1	NO	Local
786	1	1	4.7	1	0.3	1	1	1.9	0	1	1	1	1	Good		6/25/2018	1	NO	Local
787	1	1	3.5	1	.9	1	1	1.4	1	1	1	1	1	Good		6/25/2018	0	YES	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
788	1	1	5.6	1	.3	0	1	.6	0	0	0	0	1	Fair		6/25/2018	5	NO	Local
789	1	1	2.9	1	.5	1	1	.9	0	0	0	0	1	Fair		6/26/2018	4	NO	Local
790	1	1	4.1	1	0.8	0	1	1.5	1	0	0	0	0	Poor		6/26/2018	5	NO	Local
791	1	1	2.9	1	.5	1	1	1.3	1	1	1	1	1	Good	water valve in landing	6/26/2018	0	YES	Local
792	1	1	1.9	1	0.4	1	1	1.4	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
793	1	1	3.3	1	1.0	1	0	2.8	1	0	0	0	1	Fair		6/26/2018	4	NO	Local
794	1	1	3.8	1	0.6	1	1	1.6	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
795	1	1	4.3	1	0.3	1	1	1.5	1	0	0	0	1	Good		6/26/2018	3	NO	Local
796	1	1	1.6	1	.2	1	1	1.2	1	0	0	0	1	Fair		6/26/2018	3	NO	Local
797	1	1	5.9	1	0.1	1	1	0.4	1	0	0	0	1		1.5" or greater gap	6/26/2018	3	NO	Local
798	1	1	6.1	1	0.2	1	1	0.3	1	0	0	0	1	Good		6/26/2018	3	NO	Local
799	1	1	3.0	1	1.5	1	1	1.1	1	1	1	1	1	Good		6/26/2018	0	YES	Local
800	1	1	.3	1	.7	1	1	.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
801	1	1	1.4	1	0.2	1	1	0.9	1	1	1	1	1	Good		6/26/2018	0	YES	State
802	1	1	4.8	1	0.0	1	0	2.1	1	1	1	1	1	Good		6/26/2018	1	NO	Local
803	1	1	0.1	1	0.3	1	1	0.7	1	1	1	1	1	Good		6/26/2018	0	YES	State
805	1	1	.5	1	.1	1	0	2.1	0	1	1	1	1	Good		6/26/2018	2	NO	State
806	1	1	4.3	1	0.0	1	1	1.0	1	1	1	1	1	Good		6/26/2018	0	YES	State
807	1	1	3.3	1	.2	1	1	.4	1	1	1	1	1	Good		6/26/2018	0	YES	State
808	1	1	3.9	1	0.4	1	1	0.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
809	1	1	2.4	1	.2	1	1	1.0	1	1	1	1	1	Good		6/26/2018	0	YES	State
810	1	1	0.1	1	0.1	1	1	0.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
811	1	1	0.1	1	0.1	1	1	0.8	1	1	1	1	1	Good		6/26/2018	0	YES	State
812	1	1	2.0	1	.8	1	1	.6	1	1	1	1	1	Good		6/26/2018	0	YES	State
813	1	1	4.5	1	.6	1	1	1	1	1	1	1	1	Good		6/26/2018	0	YES	State
814	1	1	2.9	1	.5	1	1	1.0	1	1	1	1	1	Good		6/26/2018	0	YES	State
815	1	1	3.1	1	0.1	1	1	1.6	1	1	1	1	1	Good		6/26/2018	0	YES	State
816	1	1	3.1	1	0.0	1	1	1.6	1	1	1	1	1	Good		6/26/2018	0	YES	State
817	1	1	4.4	1	0.2	1	1	0.5	1	1	1	1	1	Good		6/26/2018	0	YES	State
818	1	1	2.9	1	.5	1	1	.4	1	1	1	1	1	Good		6/26/2018	0	YES	State
821	1	1	0.1	1	0.5	1	1	0.9	1	1	1	1	1	Fair	The curb ramp is very dirty	6/26/2018	0	YES	State
822	1	1	4.2	1	.4	1	1	.9	1	1	1	1	1	Good		6/26/2018	0	YES	Local
823	1	1	2.8	1	0.5	1	1	0.4	1	1	1	1	1	Good		6/26/2018	0	YES	Local
824	1	1	2.3	1	.2	1	1	.7	1	1	1	1	1	Good	water valve	6/26/2018	0	YES	Local
825	1	1	4.2	1	1.0	1	1	1.5	1	1	1	1	1	Good		6/26/2018	0	YES	Local
826	1	1	.7	1	.6	1	1	.7	0	1	1	1	1	Good		6/26/2018	1	NO	Local
827	1	1	4.9	1	0.1	1	0	2.1	1	0	1	1	0	Good		6/26/2018	3	NO	Local
828	1	1	4.1	1	0.1	1	1	1.8	1	0	1	1	0	Good		6/26/2018	2	NO	Local
829	1	1	3.0	1	1.4	1	1	.8	1	0	1	1	1	Good		6/26/2018	1	NO	Local
830	1	1	3.2	1	1.0	1	1	1.3	0	1	1	1	1	Good		6/26/2018	1	NO	Local
831	1	1	1.3	1	.9	1	1	.7	0	1	1	1	1	Good		6/26/2018	1	NO	Local
832	1	1	1.5	1	1.3	1	0	1.0	0	0	1	1	1	Good		6/26/2018	3	NO	Local
833	1	1	2.6	1	0.8	1	1	1.0	1	1	1	1	1	Good		6/26/2018	0	YES	Local
834	1	1	.5	1	.8	1	1	1.2	0	1	1	1	1	Good		6/26/2018	1	NO	Local
835	1	1	1.7	1	0.4	1	1	1.3	1	1	1	1	1	Good		6/26/2018	0	YES	Local
836	1	1	1.9	1	.4	1	1	.9	0	1	1	1	1	Good		6/26/2018	1	NO	Local
837	1	1	1.9	1	0.1	1	1	1.5	1	1	1	1	1	Good		6/26/2018	0	YES	Local
838	1	1	.8	1	1.2	1	1	no landing	1	1	1	1	1	Good		6/26/2018	0	YES	Local
839	1	1	4.5	1	0.1	1	1	1.1	1	1	1	1	0	Good	Water gate valve sticking up in sidewalk.	6/26/2018	1	NO	Local
840	1	1	2.6	1	1.3	1	1	2.5	1	0	1	1	1	Good		6/26/2018	1	NO	State
841	1	1	0.3	1	1.4	1	1	1.1	1	1	1	1	1	Good		6/26/2018	0	YES	Local
842	1	1	2.1	1	0.9	1	1	0.7	1	1	1	1	0	Good		6/26/2018	1	NO	Local
843	1	1	1.9	1	1.9	1	1	1.9	0	0	1	1	1	Good		6/26/2018	2	NO	State
844	1	1	1.5	1	1.8	1	0	2.2	1	0	1	1	1	Good		6/26/2018	2	NO	State
845	1	1	2.0	1	2.0	1	1	2.2	0	0	1	1	1	Good		6/26/2018	2	NO	State
846	1	1	6.4	0	2.5	1	0	6.0	0	0	1	1	1	Good		6/26/2018	4	NO	Local
847	1	1	3.0	1	1.6	1	1	1.5	1	1	1	1	0	Good		6/26/2018	1	NO	Local
848	1	1	0.3	1	0.7	1	1	1.9	1	1	1	1	1	Fair	Very dirty	6/26/2018	0	YES	Local
849	1	1	2.7	1	0.8	1	1	1.9	1	1	1	1	1	Fair	Very dirty	6/26/2018	0	YES	Local
850	1	1	9.3	1	1.1	1	0	3.4	1	1	1	1	1	Fair	little lip	6/26/2018	1	NO	Local
851	1	1	1.0	1	0.4	1	1	1.5	1	1	1	1	1	Good		6/26/2018	0	YES	Local
852	1	1	1.7	1	0.9	1	1	1.4	1	1	1	1	1	Good		6/26/2018	0	YES	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
853	1	1	9.9	1	.2	1	0	4.6	1	1	1	1	1	Good		6/26/2018	1	NO	Local
854	1	1	3.2	1	0.4	1	1	1.3	1	0	1	1	1	Good		6/26/2018	1	NO	Local
855	1	1	0.5	1	1.2	1	1	1.3	1	1	1	1	1	Fair	A chunk of the truncated domes has been sheared off.	6/26/2018	0	YES	Local
856	1	1	0.5	0	2.1	1	1	1.6	1	0	1	1	0	Fair		6/26/2018	3	NO	Local
857	1	1	1.0	0	4.0	1	0	3.7	0	0	1	1	1	Good		6/26/2018	4	NO	Local
858	1	1	4.8	0	3.5	1	0	2.7	0	1	1	1	1	Fair		6/26/2018	3	NO	Local
859	1	1	.7	1	.1	1	1	1.7	0	1	1	1	1	Good		6/26/2018	1	NO	Local
860	1	1	3.6	1	.9	0	1	.8	0	0	0	0	1	Fair		6/26/2018	5	NO	Local
861	1	0	13.3	1	1.1	1	0	2.1	1	0	0	0	0	Fair		6/26/2018	6	NO	Local
863	1	0	9.2	0	6.7	1	0	4.3	1	0	0	0	1	Fair		6/26/2018	6	NO	Local
864	1	1	.7	1	2.0	1	1	1.5	0	0	0	0	1	Fair		6/26/2018	4	NO	Local
865	1	0	9.7	0	3.9	1	0	4.2	1	0	0	0	1	Fair		6/26/2018	6	NO	Local
866	1	1	5.8	0	2.9	1	0	2.1	1	0	0	0	1	Fair		6/26/2018	5	NO	Local
867	1	1	.7	1	.3	1	1	.4	1	1	1	1	1	Good		6/26/2018	0	YES	Local
868	1	1	2.2	1	0.4	1	1	0.4	1	1	1	1	1	Good		6/26/2018	0	YES	Local
869	1	1	1.2	1	.8	1	1	.3	1	1	1	1	1	Good		6/26/2018	0	YES	State
870	1	1	0.8	1	0.1	1	1	0.3	1	1	1	1	1	Good		6/26/2018	0	YES	State
871	1	1	3.1	1	0.5	1	1	2.4	1	1	1	1	1	Good		6/26/2018	0	YES	Local
872	1	1	3.2	1	.2	1	1	1.8	1	1	1	1	1	Good	water valve	6/28/2018	0	YES	Local
873	0	0		0		0	0		0	0	0	0	0		1.5" gap or greater in elevation by the sidewalk.	6/28/2018	10	NO	Local
874	1	1	4.7	1	.1	1	1	1.5	0	1	1	1	1	Good		6/28/2018	1	NO	Local
875	1	0	9.2	0	2.2	1	0	3.3	0	0	1	1	1	Good		6/28/2018	5	NO	Local
876	1	1	4.1	0	.1	1	1	.9	1	1	1	1	1	Good		6/28/2018	1	NO	Local
877	1	1	4.7	1	.2	1	0	2.1	0	0	1	1	1	Good		6/28/2018	3	NO	Local
878	1	1	7.3	1	.5	1	0	.8	0	0	1	1	1	Good		6/28/2018	3	NO	Local
879	1	1	5.2	1	0	1	1	1.9	0	0	1	1	1	Good		6/28/2018	2	NO	Local
880	0	0		0		0	0		0	0	0	0	0			6/28/2018	10	NO	Local
881	1	1	4.8	1	.9	1	1	1.9	0	1	1	1	1	Good		6/28/2018	1	NO	Local
882	1	1	6.5	1	1.7	1	0	2.4	1	1	1	1	1	Good		6/28/2018	1	NO	Local
883	1	0	9.2	1	.4	0	0	2.1	0	0	0	0	1	Fair		6/28/2018	7	NO	Local
885	1	0	15.2	0	3.0	0	0	3.1	0	0	0	0	1	Fair		6/28/2018	8	NO	Local
886	1	1	5.6	1	1.4	1	1	1.4	1	0	1	1	1	Good		6/28/2018	1	NO	Local
888	1	1	7.9	1	.1	1	1	1.1	0	0	0	0	1	Fair		6/28/2018	4	NO	Local
889	1	1	5.1	1	1.9	1	0	2.1	0	0	1	1	1	Good		6/28/2018	3	NO	Local
890	1	1	6.2	1	1.2	1	1	1.4	0	1	1	1	1	Good	a little dip by the curb	6/28/2018	1	NO	Local
891	1	1	3.2	1	.2	1	1	.6	1	0	1	1	1	Good		6/28/2018	1	NO	Local
892	1	1	3.2	1	0.2	1	1	1.0	1	0	1	1	1	Good		6/29/2018	1	NO	Local
893	1	1	.3	1	.3	1	1	1.7	1	1	1	1	1	Good		6/29/2018	0	YES	Local
894	1	1	2.5	1	0.4	1	1	1.2	1	0	1	1	1	Good		6/29/2018	1	NO	Local
895	1	1	2.3	1	.3	1	1	1.0	1	1	1	1	1	Good		6/29/2018	0	YES	Local
896	1	1	1.9	1	0.3	1	1	1.6	1	0	1	1	1	Good		6/29/2018	1	NO	Local
897	1	1	2.6	1	.4	1	1	1.6	1	1	1	1	1	Good		6/29/2018	0	YES	Local
898	1	1	1.9	1	.5	1	1	1.6	1	1	1	1	1	Good		6/29/2018	0	YES	Local
899	1	1	4.9	1	0.6	1	1		1	0	1	1	1	Good	1.6	6/29/2018	1	NO	Local
900	1	1	2.8	1	0.0	1	1	1.6	1	0	1	1	1	Good		6/29/2018	1	NO	Local
901	1	1	3.1	1	0.3	1	1	1.9	1	0	1	1	1	Good		6/29/2018	1	NO	Local
903	1	1	3.1	1	.3	1	1	1.1	1	1	1	1	1	Good		6/29/2018	0	YES	Local
904	1	1	3.7	1	0.3	1	1		1	0	1	1	1	Good	1.2	6/29/2018	1	NO	Local
905	1	1	2.3	1	.6	1	1	1.5	1	1	1	1	1	Good		6/29/2018	0	YES	Local
906	1	1	1.5	1	.4	1	0	na	0	1	1	1	1	Good	no landing	6/29/2018	2	NO	State
907	1	1	1.8	1	.1	1	0	2.2	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
908	1	1	3.4	1	0.8	1	1	2.1	1	0	0	0	1	Fair		6/29/2018	3	NO	Local
909	1	1	3.3	1	.3	1	1	1.5	1	0	1	1	1	Good		6/29/2018	1	NO	Local
910	1	1	0.7	1	0.3	1	1	0.5	1	0	0	0	1	Good		6/29/2018	3	NO	Local
911	1	1	4.4	1	.9	0	1	1.9	1	0	0	0	1	Fair		6/29/2018	4	NO	Local
912	1	1	3.9	1	0.3	1	1	0.3	1	0	0	0	1	Good		6/29/2018	3	NO	Local
913	1	1	2.8	1	.7	1	1	.8	0	0	0	0	1	Fair		6/29/2018	4	NO	Local
914	1	1	1.7	1	.5	1	1	1.3	1	1	1	1	1	Good		6/29/2018	0	YES	Local
915	1	1	2.0	1	1.1	1	1	0.7	1	1	1	1	1	Good		6/29/2018	0	YES	Local
916	1	1	3.3	1	0.3	1	1	1.3	1	1	1	1	1	Good		6/29/2018	0	YES	Local
917	1	1	2.9	1	0.0	1	1	1.4	1	1	1	1	1	Good		6/29/2018	0	YES	Local

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction	
918	1	1	1.5	1	0.4	1	1	1.8	1	1	1	1	1	1	Good	6/29/2018	0	YES	Local	
919	1	1	3.6	1	.5	1	1	.9	0	1	1	1	1	1	Good	6/29/2018	1	NO	Local	
920	1	1	1.6	1	1.4	1	1	0.8	1	1	1	1	1	1	Good	6/29/2018	0	YES	Local	
921	1	1	1.8	1	0.3	1	1	1.9	1	1	1	1	1	1	Good	6/29/2018	0	YES	Local	
922	1	1	2.0	1	1.4	1	1	1.9	1	1	1	1	1	1	Good	6/29/2018	0	YES	Local	
923	1	1	3.1	1	1.3	1	1	1.0	1	1	1	1	1	1	Good	6/29/2018	0	YES	Local	
924	1	1	0.7	1	0.5	1	1	0.4	1	0	1	1	0	1	Good	6/29/2018	2	NO	Local	
925	1	1	2.5	1	0.3	1	1	0.5	1	1	1	1	1	1	Good	6/29/2018	0	YES	Local	
926	1	1	4.0	1	.8	1	1	1.1	1	0	0	0	1	1	Fair	6/29/2018	3	NO	Local	
927	1	1	3.2	1	1.2	0	1	1.2	1	0	0	0	1	1	Fair	6/29/2018	4	NO	Local	
928	1	1	2.9	1	.2	1	1	.6	0	0	0	0	1	1	Fair	6/29/2018	4	NO	Local	
929	1	1	5.0	1	.9	1	1	1.2	0	0	1	1	1	1	Good	6/29/2018	2	NO	Local	
930	1	1	.9	1	1.0	1	1	.3	0	0	0	1	1	1	Good	6/29/2018	3	NO	Local	
931	1	1	3.0	1	1.1	1	1	.2	1	0	0	1	1	1	Good	6/29/2018	2	NO	Local	
932	1	1	1.9	0	2.4	1	1	1.8	0	0	0	1	1	1	Good	6/29/2018	4	NO	Local	
933	1	1	1.9	0	2.1	1	1	1.3	1	0	1	1	1	1	Good	6/29/2018	2	NO	Local	
934	1	1	1.2	1	.5	1	1	.8	1	0	1	1	1	1	Good	6/29/2018	1	NO	Local	
935	1	1	3.3	1	1.0	1	1	.9	1	0	1	1	1	1	Good	6/29/2018	1	NO	Local	
936	1	1	1.9	1	.5	1	0	3.0	1	0	0	0	1	1	Fair	6/29/2018	4	NO	Local	
937	1	1	3.5	1	.3	1	1	.7	0	0	0	0	1	1	Fair	6/29/2018	4	NO	Local	
938	1	1	1.7	0	3.0	1	0	2.8	1	0	1	1	1	1	Good	6/29/2018	3	NO	Local	
939	1	1	1.2	1	0.1	1	1	0.5	1	0	1	1	1	1	Good	6/29/2018	1	NO	Local	
940	1	1	1.0	1	0.1	1	1	0.5	1	0	1	1	1	1	Good	6/29/2018	1	NO	Local	
941	1	1	1.3	1	.7	1	1	1.6	0	1	1	1	1	1	Good	6/29/2018	1	NO	Local	
942	1	1	2.0	1	0.2	1	1	1.8	0	1	1	1	1	1	Good	6/29/2018	1	NO	Local	
943	1	1	0.8	1	0.1	1	0	2.2	0	1	1	1	1	1	Good	6/29/2018	2	NO	Local	
944	1	1	2.6	1	.1	1	1	2.1	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
945	1	1	2.3	1	.3	1	1	.9	1	1	1	1	1	1	Good	7/2/2018	0	YES	Local	
946	1	1	3.6	1	.1	1	1	.6	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
947	1	1	.9	0	2.3	1	1	.2	1	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
948	1	1	3.3	1	1.4	1	0	5.7	1	0	0	0	1	1	Fair	The truncated domes have been scrapped away or removed.	7/2/2018	4	NO	Local
949	1	1	4.6	1	.3	1	1	.7	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
950	1	1	.5	1	1.5	1	0	3.6	0	0	0	0	1	1	Fair	7/2/2018	5	NO	Local	
951	1	1	1.5	1	1.1	1	0	3.4	1	0	1	1	1	1	Good	7/2/2018	2	NO	Local	
952	1	1	3.8	1	1.9	1	0	2.1	1	0	1	1	1	1	Good	7/2/2018	2	NO	Local	
953	1	1	.8	1	.7	1	1	.6	1	0	1	1	1	1	Good	7/2/2018	1	NO	Local	
954	1	1	3.9	1	1.4	1	1		1	0	1	1	1	1	Good	7/2/2018	1	NO	Local	
955	1	1	1.3	1	.3	1	1	1.0	0	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
956	1	1	2.0	1	.1	1	1	1.0	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
957	1	1	1.5	1	1.1	1	1	.7	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
958	1	1	1.9	1	1.6	1	0	4.1	1	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
959	1	1	4.4	0	2.5	1	1	.5	1	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
960	1	1	.5	1	1.9	1	1	1.7	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
961	1	1	.8	1	1.1	1	1	1.2	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
962	1	1	1.2	1	1.2	1	1	1.6	0	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
963	1	1	.9	1	.9	1	1	1.3	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
964	1	1	2.2	1	1.8	1	1	1.5	0	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
965	1	1	1.1	1	0.8	1	1	2.1	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
966	1	1	5.9	0	4.2	1	1	1.5	0	0	0	0	1	1	Fair	7/2/2018	5	NO	Local	
967	1	1	1.0	1	1.6	1	1	0.5	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
968	1	1	4.4	1	.5	1	0	3.0	1	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
969	1	1	1.8	1	.9	1	1	1.0	1	0	0	0	1	1	Poor	a lot of cracking, circle holes in trail	7/2/2018	3	NO	Local
970	1	1	6.7	1	0.5	1	0	3.5	1	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
971	1	1	.4	0	3.1	1	1	.7	0	0	0	0	1	1	Fair	7/2/2018	5	NO	Local	
972	1	1	.8	0	3.3	1	1	1.5	0	0	0	0	1	1	Fair	7/2/2018	5	NO	Local	
973	1	1	3.2	1	1.7	1	1	1.2	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
975	1	1	.4	1	.5	1	1	.7	0	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
976	1	1	1.3	1	.1	1	1	.8	0	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
977	1	1	.3	1	1.6	1	1	1.3	0	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	
978	1	1	4.1	1	.5	1	1	1.1	1	0	0	0	1	1	Fair	7/2/2018	3	NO	Local	
979	1	1	.4	1	.6	1	1	1.8	0	0	0	0	1	1	Fair	7/2/2018	4	NO	Local	

OBJECTID	If walk/trail crosses curb, is there a curb ramp?	Is the Running slope 8.3% or less?	What is the running slope of the curb ramp?	Is the cross slope 2% or less?	What is the cross slope of the curb ramp?	Is the curb ramp width 48" or wider?	Is the Landing 48in sq or more with cross slope 2% or less any dir?	What is the max landing slope?	Is the curb ramp flares slopes 10% or less?	Detectible warnings extend the full width of the curb ramp?	Is approx 75% of truncated domes in good condition?	Do the truncated domes contrast with adjacent surfaces?	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the curb ramp?	Notes	EditDate	# of Non Compliant	Compliant	Jurisdiction
980	1	1	3.9	1	.1	1	1	.7	0	0	0	0	1	Fair		7/2/2018	4	NO	Local
981	1	1	2.5	1	1.1	1	1	1.2	1	0	0	0	1	Fair		7/2/2018	3	NO	Local
982	1	1	2.3	1	1.0	1	1	1.6	1	0	0	0	1	Fair		7/2/2018	3	NO	Local
983	1	1	1.2	1	1.9	1	0	2.3	1	0	0	0	1	Fair		7/2/2018	4	NO	Local
984	1	1	.8	1	1.8	1	1	1.5	0	0	0	0	1	Fair		7/2/2018	4	NO	Local
985	1	1	1.0	1	0.4	1	0	2.1	1	0	0	0	1	Good		7/2/2018	4	NO	Local
986	1	1	0.4	1	0.7	1	1	1.2	1	0	0	0	1	Good		7/2/2018	3	NO	Local
987	1	1	3.7	1	1.8	1	1	1.5	1	0	0	0	1	Fair	bump after concrete portion, foundation concrete in middle by landing	7/2/2018	3	NO	Local
988	1	1	2.2	1	.6	1	1	1.6	1	0	0	0	1	Fair		7/2/2018	3	NO	Local
989	1	1	3.4	1	.5	1	1	1.3	0	0	1	1	1	Good		7/2/2018	2	NO	Local
990	1	1	3.9	1	0.4	1	1	1.5	1	0	1	1	1	Good		7/2/2018	1	NO	Local

TOTAL:	937
# Compliant:	158
% Compliant:	17%

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
3	1	1	0	N/A	N/A	1	1	1	Fair	vault in sidewalk with gap over 1.5"	6/25/2018	1	NO	Local
4	1	1	0	N/A	N/A	1	1	0	Good	grass growing in cracks of sidewalk	6/25/2018	2	NO	Local
5	1	1	0	N/A	N/A	1	0	1	Poor	uphevel in a lot of area amd grass. nothing greater than 1.5".	6/25/2018	2	NO	Local
6	1	1	0	N/A	N/A	1	0	0	Poor	bushes over hanging and large gap	6/25/2018	3	NO	Local
7	1	1	0	N/A	N/A	1	1	0	Fair	There is a lot of vegetation growth in the sidewalk cracks. There is tree & bush overhang in walking	6/25/2018	2	NO	Local
8	1	1	1	N/A	N/A	1	1	1	Poor	a lot of grass and uphevel. nothing greater than 1.5"	6/25/2018	0	YES	Local
9	1	1	0	N/A	N/A	1	1	0	Fair	There is a lot of vegetation growth in the cracks of the sidewalk. Bush overhang	6/25/2018	2	NO	Local
10	1	0	0	N/A	N/A	1	1	1	Good	good condition just narrow	6/25/2018	2	NO	Local
11	1	1	0	N/A	N/A	1	1	0	Poor	grass growing in sidewalk, post kind of sticking up and not very level.	6/25/2018	2	NO	Local
12	1	0	1	N/A	N/A	1	1	1	Fair		6/25/2018	1	NO	Local
13	1	1	1	N/A	N/A	1	1	1	Fair	about 1" gap just south of tracks	6/25/2018	0	YES	Local
14	1	1	1	N/A	N/A	1	0	1	Fair	low spots that kind of dip in center	6/25/2018	1	NO	Local
15	1	1	0	N/A	N/A	1	1	0	Fair	Missing pieces of concrete in the sidewalk. Tree overhang. 1.5" elevation change.	6/25/2018	2	NO	Local
16	1	1	0	N/A	N/A	1	1	0	Good	Sidewalk shifts a little bit. Bush overhang onto sidewalk	6/25/2018	2	NO	Local
17	1	1	0	N/A	N/A	1	0	0	Poor	1.5% gap, cracking, grass,	6/25/2018	3	NO	Local
18	1	1	0	N/A	N/A	1	1	1	Fair	sidewalk good, trees are in the way	6/25/2018	1	NO	Local
19	1	1	0	N/A	N/A	1	1	0	Good	cracks but no major hazards	6/25/2018	2	NO	Local
20	1	1	0	N/A	N/A	1	1	1	Fair	worn down concrete for bumpy surface	6/25/2018	1	NO	Local
21	1	0	1	N/A	N/A	1	0	0	Poor	Vegetation growing in cracks. Broken Concrete. Tree overhang. 1.5" gap in elevation.	6/25/2018	3	NO	Local
22	1	1	1	N/A	N/A	1	0	1	Fair	one panel that is cracked horribly, rest isnt too bad	6/25/2018	1	NO	Local
23	1	1	1	N/A	N/A	1	1	0	Fair	The sidewalk on this stretch is in good condition except for this location. Gap in sidewalk.	6/25/2018	1	NO	Local
24	1	1	1	N/A	N/A	1	0	0	Poor	there are a few 1.5" gaps, along with a dirt sidewalk location. high spots in center of sidewalk	6/25/2018	2	NO	Local
25	1	1	1	N/A	N/A	1	1	0	Fair	Gaps in the concrete. Vegetation growth in cracks.	6/25/2018	1	NO	Local
26	1	1	1	N/A	N/A	1	1	1	Fair	Vegetation in cracks of sidewalk	6/25/2018	0	YES	Local
27	1	1	1	N/A	N/A	1	1	0	Poor	lots of grass, cracking, drop off locations	6/25/2018	1	NO	Local
28	1	1	2	N/A	N/A	1	1	1	Good		6/25/2018	0	YES	Local
29	1	1	1	N/A	N/A	1	1	0	Fair	1.5" gap	6/25/2018	1	NO	Local
30	1	1	1	N/A	N/A	1	1	0	Poor	Vegetation growth in the cracks of the sidewalk.	6/25/2018	1	NO	Local
31	1	1	0	N/A	N/A	1	1	1	Fair	low trees and bushes in walk way	6/25/2018	1	NO	Local
32	1	1	0	N/A	N/A	1	1	1	Fair	stretch that has a lot of grass growing over it	6/25/2018	1	NO	Local
33	1	1	1	N/A	N/A	1	1	0		1.5" or larger gaps in sidewalk. Vegetation growth in cracks of sidewalk	6/25/2018	1	NO	Local
34	1	1	0	N/A	N/A	1	0	0	Fair	Sidewalk heaved up. 1.5" or greater gap in elevation.	6/25/2018	3	NO	Local
35	1	1	0	N/A	N/A	0	1	0	Fair	Vegetation in the cracks of the sidewalk. 1.5" or greater gap in elevation	6/25/2018	3	NO	Local
36	1	1	0	N/A	N/A	1	1	1	Good	little cracking otherwise good	6/25/2018	1	NO	Local
38	1	1	0	N/A	N/A	1	1	0	Fair	minor cracking but nothing major, some wearing towards end of blovk	6/25/2018	2	NO	Local
39	1	1	0	N/A	N/A	1	0	1	Fair	Tree roots heaved up sidewalk. Vegetation growth in cracks of the sidewalk.	6/25/2018	2	NO	Local
40	1	1	0	N/A	N/A	1	1	1	Good		6/25/2018	1	NO	Local
41	1	1	0	N/A	N/A	1	0	1	Fair	Vegetation growth in the cracks of the sidewalk. Tree overhang on sidewalk.	6/25/2018	2	NO	Local
42	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/25/2018	1	NO	Local
43	1	1	0	N/A	N/A	1	1	1	Good	sidewalk good. small bush needs trimming	6/25/2018	1	NO	Local
44	1	1	0	N/A	N/A	1	1	1	Fair	cracking, grass, trim bush	6/25/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
45	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the sidewalk.	6/25/2018	2	NO	Local
46	1	1	0	N/A	N/A	1	0	1	Fair	cracking a few gaps but less than 1"	6/25/2018	2	NO	Local
47	1	1	0	N/A	N/A	1	1	0	Poor	Vegetation growth in the cracks of the sidewalk. 1.5" or greater gaps. Sidewalk deteriorating.	6/25/2018	2	NO	Local
48	1	1	0	N/A	N/A	1	0	1	Fair	some parts of sidewalk look newer, some older where it has high point in middle	6/25/2018	2	NO	Local
49	1	1	0	N/A	N/A	1	1	1	Good	New sidewalk	6/25/2018	1	NO	Local
50	1	1	0	N/A	N/A	0	1	0	Fair	a new and slightly wider portion, some with grass and slight high pt, concrete wearing	6/25/2018	3	NO	Local
51	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk. Bush overhang onto sidewalk.	6/25/2018	1	NO	Local
52	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk. Brush overhang onto sidewalk.	6/25/2018	1	NO	Local
53	1	1	0	N/A	N/A	1	1	1	Fair	Sidewalk has a lot of cracks in the pavement. Some brush overhang onto sidewalk.	6/25/2018	1	NO	Local
54	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the sidewalk. 1.5" or greater gap in sidewalk crack.	6/25/2018	2	NO	Local
55	1	1	0	N/A	N/A	1	0	0	Poor	a lot of cracks, some worn concrete, upheaving in specific areas. large gap	6/25/2018	3	NO	Local
56	1	1	0	N/A	N/A	1	1	0	Fair	portion where grass is taking over, small cracks minor gal	6/25/2018	2	NO	Local
57	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the sidewalk. Bush and tree overhang onto sidewalk.	6/25/2018	2	NO	Local
58	1	1	N/A	N/A	N/A	1	1	1	Good	minor cracking, little grass	6/25/2018	0	YES	Local
59	1	1	1	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/25/2018	0	YES	Local
60	1	1	0	N/A	N/A	1	0	0	Poor	a couple gaps greater than 1.5" in similar panels major cracking, qearing along whole stretch	6/25/2018	3	NO	Local
61	1	1	0	N/A	N/A	1	1	1	Fair		6/25/2018	1	NO	Local
62	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the sidewalk. 1.5" or greater gap.	6/25/2018	2	NO	Local
63	1	1	N/A	N/A	N/A	1	1	1	Good	most are new panels, old panels and meeting points look good.	6/25/2018	0	YES	Local
64	1	1	N/A	N/A	N/A	1	1	1	Good	most of it new, old panels and connection point are good	6/25/2018	0	YES	Local
65	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the sidewalk. 1.5" or greater gap in elevation.	6/25/2018	2	NO	Local
66	1	1	0	N/A	N/A	1	1	1	Good	a lot of spot repairs done, slight gapping on a few panels but about 1 inch	6/25/2018	1	NO	Local
67	1	1	0	N/A	N/A	1	1	1	Good	spot repairs, some grass and cracking in old locations	6/25/2018	1	NO	Local
68	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap	6/25/2018	2	NO	Local
69	1	1	0	N/A	N/A	1	1	1	Fair	quite a bit of longitudinal cracking, weared concrete	6/25/2018	1	NO	Local
70	1	1	0	N/A	N/A	1	1	0	Fair	a lot of grass, 2 panels with big gap	6/25/2018	2	NO	Local
71	1	1	0	N/A	N/A	1	0	1	Poor	Vegetation growth in the cracks of the sidewalk.	6/25/2018	2	NO	Local
72	1	1	0	N/A	N/A	1	1	1	Fair	longitudinal cracking	6/25/2018	1	NO	Local
73	1	1	0	N/A	N/A	1	0	1			6/25/2018	2	NO	Local
74	1	1	0	N/A	N/A	1	1	1	Fair	Sidewalk is not complete. Tree overhang onto sidewalk.	6/25/2018	1	NO	Local
75	1	1	0	N/A	N/A	1	1	0	Fair	longitudinal cracking, grass and unlevel	6/25/2018	2	NO	Local
76	1	1	0	N/A	N/A	1	0	0	Fair	1.5" or greater gap in elevation	6/25/2018	3	NO	Local
77	1	1	0	N/A	N/A	1	1	0	Poor	a lot of cracking, grass and somw upheaving	6/25/2018	2	NO	Local
78	1	1	0	N/A	N/A	1	1	1	Good	cracking on 2 or 3 panels	6/25/2018	1	NO	Local
79	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/25/2018	1	NO	Local
80	1	1	0	N/A	N/A	1	1	1			6/25/2018	1	NO	Local
81	1	1	0	N/A	N/A	1	0	1	Good		6/25/2018	2	NO	Local
82	1	1	0	N/A	N/A	1	1	0	Good	1.5" or greater gap in elevation	6/25/2018	2	NO	Local
83	1	1	0	N/A	N/A	1	1	1	Good		6/25/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
84	1	1	N/A	N/A	N/A	1	1	0	Good		6/25/2018	1	NO	Local
85	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/25/2018	1	NO	Local
86	1	1	0	N/A	N/A	1	0	1	Fair	larger cracks with small gaps	6/25/2018	2	NO	Local
88	1	1	0	N/A	N/A	1	1	1	Good		6/25/2018	1	NO	Local
89	1	1	N/A	N/A	N/A	1	0	0	Fair	3/4" gap, cracking, grass	6/25/2018	2	NO	Local
90	1	1	0	N/A	N/A	1	1	1	Good		6/25/2018	1	NO	Local
91	1	1	0	N/A	N/A	1	0	1	Fair	long cracking, some broken concrete, gaps	6/25/2018	2	NO	Local
92	1	1	0	N/A	N/A	1	1	1	Fair	A lot of cracks in the sidewalk. 1.5" or greater gap in elevation	6/25/2018	1	NO	Local
93	1	1	0	N/A	N/A	1	0	0	Poor	1in gap, cracking	6/25/2018	3	NO	Local
94	1	1	0	N/A	N/A	1	1	1	Good		6/25/2018	1	NO	Local
95	1	1	N/A	N/A	N/A	1	0	0	Poor	1.5" gap, upheaving	6/25/2018	2	NO	Local
96	1	1	0	N/A	N/A	1	0	1	Fair	long cracking, grass	6/25/2018	2	NO	Local
97	1	1	0	N/A	N/A	1	1	1	Good	Tree overhang onto sidewalk.	6/25/2018	1	NO	Local
98	1	1	0	N/A	N/A	1	1	1	Good		6/25/2018	1	NO	Local
99	1	1	N/A	N/A	N/A	1	1	1	Poor	lots of cracking, grass and gaps	6/25/2018	0	YES	Local
100	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/25/2018	1	NO	Local
101	1	1	0	N/A	N/A	1	1	1	Good	minor cracking and grass	6/25/2018	1	NO	Local
102	1	1	0	N/A	N/A	1	1	1	Good	some bushes in way	6/25/2018	1	NO	Local
103	1	1	1	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/25/2018	0	YES	Local
104	1	1	0	N/A	N/A	1	1	1	Fair	grass, crack and a gap	6/25/2018	1	NO	Local
105	1	1	1	N/A	N/A	1	1	1	Good	Tree overhang onto sidewalk.	6/25/2018	0	YES	Local
106	1	1	N/A	N/A	N/A	1	0	1	Poor	1" gap, grass and cracks, east half new	6/25/2018	1	NO	Local
107	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/25/2018	1	NO	Local
108	1	1	0	N/A	N/A	1	0	1	Fair	deteriorating concrete, cracks, south 1/3 new	6/25/2018	2	NO	Local
109	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk. 1.5" or greater elevation gap.	6/25/2018	1	NO	Local
110	1	1	0	N/A	N/A	1	1	1	Fair	grass and cracks in about 1/4 of sidewalk	6/25/2018	1	NO	Local
111	1	1	0	N/A	N/A	1	1	1	Poor	Vegetation growth in the cracks of the sidewalk. Brush overhang onto sidewalk. Pavement deteriorating	6/25/2018	1	NO	Local
112	1	1	0	N/A	N/A	1	0	1	Poor	1 3/8 in gap	6/25/2018	2	NO	Local
113	1	1	0	N/A	N/A	1	1	1	Poor	deteriorating concrete, cracks, 1 in gaps	6/25/2018	1	NO	Local
114	1	1	1	N/A	N/A	1	1	1	Good		6/25/2018	0	YES	Local
115	1	1	1	N/A	N/A	1	1	1	Good		6/25/2018	0	YES	Local
116	1	1	0	N/A	N/A	1	1	1	Fair	grass and cracks. small gaps. bushes in way	6/25/2018	1	NO	Local
117	1	1	0	N/A	N/A	1	1	1	Good	minor cracking	6/25/2018	1	NO	Local
118	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the sidewalk. Tree overhang onto sidewalk.	6/25/2018	2	NO	Local
119	1	0	0	N/A	N/A	1	1	1	Fair		6/25/2018	2	NO	Local
120	1	0	0	N/A	N/A	1	1	0	Fair	Missing concrete in the sidewalk	6/25/2018	3	NO	Local
121	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the sidewalk.	6/25/2018	2	NO	Local
122	1	1	1	N/A	N/A	1	1	1	Good		6/25/2018	0	YES	Local
123	1	1	0	N/A	N/A	1	0	1	Fair	grass, cracks and some upheaving	6/26/2018	2	NO	Local
124	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap in elevation. Manhole in sidewalk.	6/26/2018	2	NO	Local
125	1	1	0	N/A	N/A	1	1	0	Fair	1.5" gap	6/26/2018	2	NO	Local
126	1	1	1	N/A	N/A	1	1	0	Good	4" gap in elevation	6/26/2018	1	NO	Local
127	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
128	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
129	1	1	0	N/A	N/A	1	0	0	Fair	some cracking and upheaving. portion in the West side is new	6/26/2018	3	NO	Local
130	1	1	0	N/A	N/A	1	1	0	Poor	a lot of cracking and unlevelness	6/26/2018	2	NO	Local
131	1	1	N/A	N/A	N/A	1	1	0	Fair	cracking, large gap along edge	6/26/2018	1	NO	Local
132	1	1	0	N/A	N/A	1	1	1	Good		6/26/2018	1	NO	Local
133	1	1	N/A	N/A	N/A	1	1	0	Fair	some cracking, chipping and bushes in way	6/26/2018	1	NO	Local
134	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
135	1	1	0	N/A	N/A	1	0	0	Good	slope is 2.2 but otherwise good condition	6/26/2018	3	NO	Local
136	1	1	0	N/A	N/A	1	1	1	Good	Tree overhang onto sidewalk	6/26/2018	1	NO	Local
137	1	1	N/A	N/A	N/A	1	0	0	Fair	small portion new, few panels with cracks and gaps	6/26/2018	2	NO	Local
138	1	1	1	N/A	N/A	1	1	0	Poor	A lot of cracking and broken up concrete. 1.5" or greater gaps.	6/26/2018	1	NO	Local
139	1	1	1	N/A	N/A	1	1	1	Fair	Tree overhang onto sidewalk.	6/26/2018	0	YES	Local
140	1	1	0	N/A	N/A	1	0	0	Fair	1 or 2 bad panels and trees in the way. 3" gap	6/26/2018	3	NO	Local
141	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
142	1	1	0	N/A	N/A	1	1	0	Good		6/26/2018	2	NO	Local
143	1	1	0	N/A	N/A	1	1	0	Fair	cracking	6/26/2018	2	NO	Local
144	1	1	0	N/A	N/A	1	1	1	Fair	some cracks	6/26/2018	1	NO	Local
146	1	1	0	N/A	N/A	1	1	0	Poor	Vegetation growth in the cracks of the sidewalk. 1.5" or greater gaps	6/26/2018	2	NO	Local
147	1	1	0	N/A	N/A	1	1	0	Fair	some cracks, light semi in sidewalk	6/26/2018	2	NO	Local
148	1	1	0	N/A	N/A	1	1	1	Poor	Vegetation growth in the cracks of the sidewalk.	6/26/2018	1	NO	Local
149	1	1	1	N/A	N/A	1	1	1	Fair		6/26/2018	0	YES	Local
150	1	1	0	N/A	N/A	1	1	0	Good	north part is really new. this ia also in good condition	6/26/2018	2	NO	Local
151	1	1	1	N/A	N/A	1	1	1	Good	Water gate valve in sidewalk	6/26/2018	0	YES	Local
152	1	1	1	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk. Tree overhang onto sidewalk.	6/26/2018	0	YES	Local
153	1	1	1	N/A	N/A	1	1	0	Good	few cracks and have brick boulevards	6/26/2018	1	NO	Local
154	1	1	1	N/A	N/A	1	1	0	Good	minor cracks and bricke in boulevard	6/26/2018	1	NO	Local
155	1	1	1	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk. Tree overhang onto sidewalk.	6/26/2018	0	YES	Local
156	1	1	1	N/A	N/A	1	1	0	Good		6/26/2018	1	NO	Local
157	1	1	1	N/A	N/A	1	1	0	Good	minor wear bricks in boulevard are bad	6/26/2018	1	NO	Local
158	1	1	1	N/A	N/A	1	1	0	Good	minot cracks, bricks in boulevard are bad	6/26/2018	1	NO	Local
159	1	1	0	N/A	N/A	1	1	0	Fair	tree growing over sidewalk, creating it to shirt and upheave	6/26/2018	2	NO	Local
160	1	1	0	N/A	N/A	1	1	1	Good	A lot of the sidewalk panels have been replaced already.	6/26/2018	1	NO	Local
161	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gaps. Vegetation growth in the cracks of the sidewalk.	6/26/2018	2	NO	Local
162	1	1	1	N/A	N/A	1	1	1	Fair	1.5" or greater gaps. Vegetation growth in the cracks of the sidewalk.	6/26/2018	0	YES	Local
163	1	1	N/A	N/A	N/A	1	1	0	Good		6/26/2018	1	NO	Local
164	1	1	1	N/A	N/A	1	1	0	Good	Electric Vault in the middle of the sidewalk. 1.5" or greater gap.	6/26/2018	1	NO	Local
165	1	1	N/A	N/A	N/A	1	0	0	Good	2.7% cross slope but concrete in good condition	6/26/2018	2	NO	Local
166	1	1	0	N/A	N/A	1	1	1	Fair	Tree overhang onto sidewalk.	6/26/2018	1	NO	Local
167	1	1	0	N/A	N/A	1	1	0	Good	not 48" throughout	6/26/2018	2	NO	Local
168	1	1	N/A	N/A	N/A	1	1	0	Fair	deteriated concrete, cracking	6/26/2018	1	NO	Local
169	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
170	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
171	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
172	1	1	N/A	N/A	N/A	1	1	1	Fair	spots of deteriated concrete	6/26/2018	0	YES	Local
173	1	1	0	N/A	N/A	1	1	1	Fair	Street light and bushes in the way of the sidewalk.	6/26/2018	1	NO	Local
174	1	1	0	N/A	N/A	1	1	1	Fair	Streetlights are in the sidewalk. Electric vault in sidewalk.	6/26/2018	1	NO	Local
175	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
176	1	1	N/A	N/A	N/A	1	1	0	Fair	cracks, deteriorating concrete, grass	6/26/2018	1	NO	Local
177	1	1	0	N/A	N/A	1	1	0	Fair	trees in way, cracking	6/26/2018	2	NO	Local
178	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
179	1	1	0	N/A	N/A	1	0	0	Fair	cracking and a few panela upheaving	6/26/2018	3	NO	Local
180	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
181	1	1	N/A	N/A	N/A	1	1	0	Fair	all brick	6/26/2018	1	NO	Local
182	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
183	1	1	1	N/A	N/A	1	1	0	Good	prett good few panels upheaving	6/26/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
184	1	1	1	N/A	N/A	1	0	0	Fair	cracking, uneven, brick amd dumpster in way	6/26/2018	2	NO	Local
185	1	1	N/A	N/A	N/A	1	0	0	Good	some upheaving and cross slope is 4.3%	6/26/2018	2	NO	Local
186	1	1	N/A	N/A	N/A	1	1	1	Good	minor cracking	6/26/2018	0	YES	Local
187	1	1	N/A	N/A	N/A	1	1	1	Good	good condition minor cracks	6/26/2018	0	YES	Local
188	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap.	6/26/2018	1	NO	Local
189	1	1	1	N/A	N/A	1	0	1	Good		6/26/2018	1	NO	Local
190	1	1	N/A	N/A	N/A	1	1	0	Fair	brick in some area, upheaving by entrance	6/26/2018	1	NO	Local
191	1	1	1	N/A	N/A	1	1	0	Good	overall good, some bricks by boulevard and utiltiy box in middle	6/26/2018	1	NO	Local
192	1	1	1	N/A	N/A	0	0	1	Good	2.2 cross slope	6/26/2018	2	NO	Local
193	1	1	N/A	N/A	N/A	1	1	0	Good	pretty level throughout but it is brick material	6/26/2018	1	NO	Local
194	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
195	1	1	N/A	N/A	N/A	1	1	0	Fair	pretty big lip	6/26/2018	1	NO	Local
196	1	1	0	N/A	N/A	1	0	1	Fair	Vegetation growth in the cracks of the sidewalk. Brush and tree overhang onto sidewalk	6/26/2018	2	NO	Local
197	1	1	0	N/A	N/A	1	0	1	Fair	2.9% cross slope, few bad panels, some new panels by edgewood	6/26/2018	2	NO	Local
198	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the curb ramp. 1.5" or greater gap. Tree and brush overhang onto	6/26/2018	2	NO	Local
199	1	1	0	N/A	N/A	1	1	0	Good	Electrical vault in sidewalk.	6/26/2018	2	NO	Local
200	1	1	1	N/A	N/A	1	1	0	Good	Centerline joint has a 1" gap in places.	6/26/2018	1	NO	Local
201	1	1	N/A	N/A	N/A	1	1	0	Good		6/26/2018	1	NO	Local
202	1	1	0	N/A	N/A	1	1	0	Good	minor cracking a little upheaving	6/26/2018	2	NO	Local
203	1	1	1	N/A	N/A	1	1	1	Good	Gas valve in sidewalk.	6/26/2018	0	YES	Local
204	1	1	0	N/A	N/A	1	1	1	Good		6/26/2018	1	NO	Local
205	1	1	0	N/A	N/A	1	1	0	Good	1" elevation gap	6/26/2018	2	NO	Local
206	1	1	0	N/A	N/A	1	1	1	Good		6/26/2018	1	NO	Local
207	1	1	0	N/A	N/A	1	1	1	Good		6/26/2018	1	NO	Local
208	1	1	0	N/A	N/A	1	1	0	Good	new on half of it	6/26/2018	2	NO	Local
209	1	1	0	N/A	N/A	1	1	1	Good		6/26/2018	1	NO	Local
210	1	1	0	N/A	N/A	0	1	1	Fair	few bad and unlevel panels	6/26/2018	2	NO	Local
211	1	1	0	N/A	N/A	1	1	0	Good	1.5" or greater gap in elevation	6/26/2018	2	NO	Local
212	1	1	0	N/A	N/A	1	1	0	Good		6/26/2018	2	NO	Local
213	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/26/2018	1	NO	Local
214	1	1	0	N/A	N/A	1	1	1	Good		6/26/2018	1	NO	Local
215	1	1	0	N/A	N/A	1	1	1	Good	City Water Valve in the sidewalk	6/26/2018	1	NO	Local
216	1	1	N/A	N/A	N/A	1	1	1	Good	gas valve in sidewalk	6/26/2018	0	YES	Local
217	1	1	N/A	N/A	N/A	1	1	0	Good		6/26/2018	1	NO	Local
218	1	1	N/A	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
219	1	1	1	N/A	N/A	1	1	1	Good	Tree overhang onto the sidewalk	6/26/2018	0	YES	Local
220	1	1	N/A	N/A	N/A	1	1	0	Good		6/26/2018	1	NO	Local
221	1	1	1	N/A	N/A	1	1	1	Good	Water gate valve sticking up in the sidewalk.	6/26/2018	0	YES	Local
222	1	1	N/A	N/A	N/A	1	0	1	Good		6/26/2018	1	NO	Local
223	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
224	1	1	N/A	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
225	1	1	N/A	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
226	1	1	1	N/A	N/A	1	1	1	Good	Water gate valve in the sidewalk	6/26/2018	0	YES	Local
227	1	1	0	N/A	N/A	1	0	0	Good	gap between curb and sidewalk	6/26/2018	3	NO	Local
228	1	1	N/A	N/A	N/A	1	0	1	Good		6/26/2018	1	NO	Local
229	1	1	N/A	N/A	N/A	1	0	1	Good		6/26/2018	1	NO	Local
230	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
231	1	1	N/A	N/A	N/A	1	0	1	Good		6/26/2018	1	NO	Local
232	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
233	1	1	1	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
234	1	1	N/A	N/A	N/A	0	1	1	Good	9.8% on pavement heaved on 2 panels	6/26/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
235	1	1	0	N/A	N/A	1	1	1	Good		6/26/2018	1	NO	Local
236	1	1	0	N/A	N/A	1	1	1	Good		6/26/2018	1	NO	Local
237	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/26/2018	1	NO	Local
238	1	1	0	N/A	N/A	1	1	1	Good	little chipping and upheaving	6/26/2018	1	NO	Local
239	1	1	0	N/A	N/A	1	0	0	Good		6/26/2018	3	NO	Local
240	1	1	0	N/A	N/A	0	1	1	Good		6/26/2018	2	NO	Local
241	1	1	N/A	N/A	N/A	1	1	1	Good		6/26/2018	0	YES	Local
242	1	1	0	N/A	N/A	1	1	0	Fair	Tree and brush overhang onto the sidewalk. Vegetation growth in cracks. 1.5" gap or greater	6/28/2018	2	NO	Local
243	1	1	0	N/A	N/A	0	1	1	Fair	5.2% running some upheaving and cracking	6/28/2018	2	NO	Local
244	1	1	0	N/A	N/A	1	1	1	Fair	some cracking, middle section new sidewalk	6/28/2018	1	NO	Local
245	1	1	0	N/A	N/A	1	0	1	Good	gap but less than 1.5	6/28/2018	2	NO	Local
246	1	1	0	N/A	N/A	1	1	1	Fair	Tree overhang onto sidewalk.	6/28/2018	1	NO	Local
247	1	1	0	N/A	N/A	1	0	1	Fair	some cracks	6/28/2018	2	NO	Local
248	1	1	0	N/A	N/A	1	1	1	Fair	cracking and grass	6/28/2018	1	NO	Local
249	1	0	0	N/A	N/A	1	1	1	Good		6/28/2018	2	NO	Local
250	1	1	0	N/A	N/A	1	1	1	Fair	long cracking deteriorating sidewalk	6/28/2018	1	NO	Local
251	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap in elevation. Vegetation growth in the cracks of the sidewalk.	6/28/2018	2	NO	Local
252	1	1	0	N/A	N/A	1	0	1	Fair	cracking	6/28/2018	2	NO	Local
253	1	1	0	N/A	N/A	1	0	0	Fair	valve sticking out like 2 inches	6/28/2018	3	NO	Local
254	1	0	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk	6/28/2018	2	NO	Local
257	1	1	0	N/A	N/A	1	1	1	Good	5.2 crossing	6/28/2018	1	NO	Local
258	1	1	0	N/A	N/A	1	1	0	Poor	Missing pavement chunks. Vegetation growth in the cracks of the sidewalk. Tree overhang	6/28/2018	2	NO	Local
259	1	1	0	N/A	N/A	1	1	1	Fair	cracking and small gaps	6/28/2018	1	NO	Local
260	1	1	0	N/A	N/A	0	1	0	Fair	Driveway ramp built into sidewalk. Vegetation growth in the cracks of the sidewalk. Tree overhang	6/28/2018	3	NO	Local
262	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap. Brush and tree overhang	6/28/2018	2	NO	Local
264	1	1	0	N/A	N/A	1	1	1	Good		6/28/2018	1	NO	Local
265	1	1	0	N/A	N/A	1	0	1	Fair	cracking and grass	6/28/2018	2	NO	Local
266	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
267	1	1	0	N/A	N/A	1	1	1	Fair	cracking and tree in way	6/28/2018	1	NO	Local
268	1	1	0	N/A	N/A	1	0	1	Fair	cracking	6/28/2018	2	NO	Local
269	1	1	0	N/A	N/A	1	1	0	Fair	Broken concrete. 1.5" or greater gap. Water & Light Department vault.	6/28/2018	2	NO	Local
270	1	1	0	N/A	N/A	1	0	1	Good		6/28/2018	2	NO	Local
271	1	1	0	N/A	N/A	1	1	1	Good		6/28/2018	1	NO	Local
272	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
273	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
274	1	1	0	N/A	N/A	1	1	0	Fair	Tree overhang onto sidewalk.	6/28/2018	2	NO	Local
275	1	1	0	N/A	N/A	1	1	0	Fair	Brush and tree overhang onto sidewalk. Vegetation growth in the cracks of the sidewalk.	6/28/2018	2	NO	Local
276	1	1	0	N/A	N/A	1	0	1	Fair	cracks and deteriorating concrete	6/28/2018	2	NO	Local
277	1	1	0	N/A	N/A	1	0	1	Good		6/28/2018	2	NO	Local
278	1	1	0	N/A	N/A	1	1	1	Fair	Tree overhang onto sidewalk. Vegetation growth in the cracks of the sidewalk.	6/28/2018	1	NO	Local
279	1	1	0	N/A	N/A	1	0	0	Poor	cracks a gap about 1.25"	6/28/2018	3	NO	Local
280	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap in elevation. Vegetation growth in the cracks of the sidewalk. Tree overhang	6/28/2018	2	NO	Local
281	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap. Brush and tree overhang. Vegetation growth in the cracks of the sidewalk.	6/28/2018	2	NO	Local
282	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
283	1	1	0	N/A	N/A	1	1	1	Poor	Concrete is starting to unravel	6/28/2018	1	NO	Local
284	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
285	1	1	0	N/A	N/A	1	1	0	Fair	Concrete is breaking up. 1.5" or greater gap. Tree overhang onto sidewalk.	6/28/2018	2	NO	Local
286	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
287	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap	6/28/2018	2	NO	Local
288	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
289	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
290	1	1	0	N/A	N/A	1	1	1	Fair	Tree overhang onto the sidewalk.	6/28/2018	1	NO	Local
291	1	1	0	N/A	N/A	1	1	1	Good		6/28/2018	1	NO	Local
292	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap. Vegetation growth in the cracks of the sidewalk.	6/28/2018	2	NO	Local
293	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap. Tree overhang onto the sidewalk.	6/28/2018	2	NO	Local
295	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
296	1	1	N/A	N/A	N/A	1	1	1	Good	most new	6/28/2018	0	YES	Local
297	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
298	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap	6/28/2018	2	NO	Local
299	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
300	1	1	0	N/A	N/A	1	1	1	Good		6/28/2018	1	NO	Local
301	1	1	0	N/A	N/A	1	0	1	Good	majority are new panels	6/28/2018	2	NO	Local
302	1	1	0	N/A	N/A	1	1	1	Fair	1.5" or greater gap. Vegetation growth in the cracks of the sidewalk.	6/28/2018	1	NO	Local
303	1	1	0	N/A	N/A	1	1	1	Fair	Sidewalk is not complete.	6/28/2018	1	NO	Local
304	1	1	0	N/A	N/A	1	0	0	Good	1.5" or greater gap along back of curb and at driveway points.	6/28/2018	3	NO	Local
305	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
306	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
307	1	1	0	N/A	N/A	1	1	1	Fair	deteriorating	6/28/2018	1	NO	Local
308	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
309	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
310	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
311	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/28/2018	1	NO	Local
312	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
313	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/28/2018	1	NO	Local
314	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk. Tree overhang onto sidewalk.	6/28/2018	1	NO	Local
315	1	1	1	N/A	N/A	1	1	1	Fair		6/28/2018	0	YES	Local
316	1	1	0	N/A	N/A	1	0	1	Good		6/28/2018	2	NO	Local
317	1	1	0	N/A	N/A	1	1	1	Fair	Mailboxes are in the sidewalk	6/28/2018	1	NO	Local
318	1	1	0	N/A	N/A	0	0	0	Poor	water valve sticking up 4 inches, mailboxes in sidewalks	6/28/2018	4	NO	Local
319	1	1	0	N/A	N/A	1	1	1	Fair	Mailboxes are in the sidewalk. Brush overhang onto sidewalk.	6/28/2018	1	NO	Local
320	1	1	0	N/A	N/A	1	1	1	Fair	mailboxes in sidewalk	6/28/2018	1	NO	Local
321	1	1	0	N/A	N/A	1	1	1	Fair	Mailboxes are in the sidewalk. Sidewalk is not complete	6/28/2018	1	NO	Local
322	1	1	0	N/A	N/A	1	0	0	Fair	mailbox is way, driveway apron is blasted apart	6/28/2018	3	NO	Local
323	1	1	0	N/A	N/A	1	1	1	Fair	Mailboxes are in the sidewalk. Sidewalk is not complete. Vegetation growth in the cracks of the SW	6/28/2018	1	NO	Local
325	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap. Sidewalk is not complete on both sides of this point.	6/28/2018	2	NO	Local
326	1	1	0	N/A	N/A	1	1	1	Fair	mailboxes and some gaps	6/28/2018	1	NO	Local
327	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
328	1	1	0	N/A	N/A	1	1	0	Good	Mailbox anything on the sidewalk. Sidewalk is not complete.	6/28/2018	2	NO	Local
329	1	1	0	N/A	N/A	1	0	1	Fair	slight gaps and mailboxes	6/28/2018	2	NO	Local
330	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
331	1	1	0	N/A	N/A	1	0	0	Fair	mailboxes	6/28/2018	3	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
332	1	1	0	N/A	N/A	1	1	1	Fair	Mailboxes are in the sidewalk	6/28/2018	1	NO	Local
333	1	1	0	N/A	N/A	1	1	1	Good	Mailboxes are in the sidewalk.	6/28/2018	1	NO	Local
334	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
335	1	1	0	N/A	N/A	1	1	0	Fair	Broken sidewalk panels.	6/28/2018	2	NO	Local
336	1	1	0	N/A	N/A	0	1	1	Good		6/28/2018	2	NO	Local
337	1	1	0	N/A	N/A	1	1	1	Good		6/28/2018	1	NO	Local
338	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
339	1	1	0	N/A	N/A	1	1	1	Good		6/28/2018	1	NO	Local
340	1	1	0	N/A	N/A	1	0	1	Fair		6/28/2018	2	NO	Local
341	1	1	0	N/A	N/A	1	1	0	Poor	1.5" or greater gap	6/28/2018	2	NO	Local
342	1	1	0	N/A	N/A	0	0	1	Fair		6/28/2018	3	NO	Local
343	1	1	0	N/A	N/A	1	1	1	Fair	Water gate valve sticking up through the sidewalk.	6/28/2018	1	NO	Local
344	1	1	0	N/A	N/A	1	1	1	Good		6/28/2018	1	NO	Local
345	1	1	0	N/A	N/A	1	1	1	Good	Some cracking throughout the sidewalk. Tree overhang onto sidewalk.	6/28/2018	1	NO	Local
346	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
347	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
349	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the sidewalk. Brush overhang onto sidewalk. 1.5" or greater gap.	6/28/2018	2	NO	Local
350	1	1	0	N/A	N/A	1	1	1	Good		6/28/2018	1	NO	Local
351	1	1	0	N/A	N/A	1	1	1	Poor	missing a part and gaps about 3/4"	6/28/2018	1	NO	Local
352	1	1	0	N/A	N/A	1	1	1	Fair	Cracks in the sidewalk	6/28/2018	1	NO	Local
353	1	1	0	N/A	N/A	1	1	1	Fair	Brush overhang onto sidewalk	6/28/2018	1	NO	Local
354	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap. Sidewalk is not complete	6/28/2018	2	NO	Local
355	1	1	0	N/A	N/A	1	1	1	Fair	Tree overhang onto sidewalk.	6/28/2018	1	NO	Local
356	1	1	0	N/A	N/A	1	1	1	Fair		6/28/2018	1	NO	Local
357	1	1	0	N/A	N/A	1	1	1	Good		6/28/2018	1	NO	Local
358	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
359	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap. Tree overhang onto sidewalk.	6/29/2018	2	NO	Local
360	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
361	1	1	0	N/A	N/A	1	1	1	Fair	cracking about .5 inches	6/29/2018	1	NO	Local
362	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
363	1	1	0	N/A	N/A	1	1	1	Poor		6/29/2018	1	NO	Local
364	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap. Tree overhang onto sidewalk.	6/29/2018	2	NO	Local
365	1	1	0	N/A	N/A	1	0	1	Fair		6/29/2018	2	NO	Local
366	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
367	1	1	0	N/A	N/A	1	1	1	Fair	looks like missing sidewalk next to agg driveway	6/29/2018	1	NO	Local
368	1	1	0	N/A	N/A	1	1	0	Good	Water gate valve sticking up out of the sidewalk.	6/29/2018	2	NO	Local
369	1	1	1	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk. Sidewalk is not complete	6/29/2018	0	YES	Local
370	1	1	0	N/A	N/A	1	1	1	Fair	slight lip	6/29/2018	1	NO	Local
371	1	1	0	N/A	N/A	1	1	0	Fair	Vegetation growth in the cracks of the sidewalk. 1.5" or greater gap	6/29/2018	2	NO	Local
372	1	1	0	N/A	N/A	1	0	1	Fair		6/29/2018	2	NO	Local
373	1	1	0	N/A	N/A	1	1	1	Fair	north portion looks new, southern portion older	6/29/2018	1	NO	Local
374	0	0	0	N/A	N/A	0	0	0		There is no sidewalk here.	6/29/2018	6	NO	Local
377	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
378	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
379	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap	6/29/2018	2	NO	Local
380	1	1	0	N/A	N/A	1	1	0	Fair	Water & Light Department vault in the sidewalk. 1.5" or greater gap.	6/29/2018	2	NO	Local
381	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap	6/29/2018	1	NO	Local
382	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
383	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
384	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
385	1	1	1	N/A	N/A	1	0	0	Good	2.1 cross slope. 1.5" or greater gap.	6/29/2018	2	NO	Local
386	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
387	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
388	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
389	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap.	6/29/2018	1	NO	Local
390	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
391	1	1	1	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
392	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
393	1	1	N/A	N/A	N/A	1	1	0	Good	huge lip between sidewalk and path by bathroom	6/29/2018	1	NO	Local
394	1	1	1	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
395	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
396	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
397	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
398	1	1	1	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
399	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
400	1	1	0	N/A	N/A	1	0	1	Fair	Grass overgrowth onto sidewalk. The sidewalk is not complete.	6/29/2018	2	NO	Local
401	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
402	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
403	1	1	0	N/A	N/A	1	1	1	Good	Most of the sidewalk is new	6/29/2018	1	NO	Local
404	1	1	0	N/A	N/A	1	1	1	Fair	Tree overhang onto the sidewalk. Grass overgrowth onto the sidewalk.	6/29/2018	1	NO	Local
405	1	1	0	N/A	N/A	1	0	1	Fair		6/29/2018	2	NO	Local
406	1	1	0	N/A	N/A	1	0	1	Good		6/29/2018	2	NO	Local
407	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
408	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
409	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
410	1	1	0	N/A	N/A	1	1	1	Fair	Mailboxes are in the sidewalk.	6/29/2018	1	NO	Local
411	1	1	1	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
412	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
413	1	1	1	N/A	N/A	1	1	1	Good	There is a dip in the shared use path	6/29/2018	0	YES	Local
414	1	1	0	N/A	N/A	1	0	0	Fair		6/29/2018	3	NO	Local
415	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
416	1	1	0	N/A	N/A	1	1	0	Fair	Water gate valve sticking up through the sidewalk. 1.5" or greater gap	6/29/2018	2	NO	Local
417	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap. Most of the sidewalk is new.	6/29/2018	1	NO	Local
418	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk. 1.5" or greater gap.	6/29/2018	1	NO	Local
419	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
420	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
421	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
422	1	1	0	N/A	N/A	1	0	1	Fair		6/29/2018	2	NO	Local
423	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
424	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap	6/29/2018	2	NO	Local
425	1	1	0	N/A	N/A	1	0	1	Good		6/29/2018	2	NO	Local
426	1	1	0	N/A	N/A	1	1	1	Poor		6/29/2018	1	NO	Local
427	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
428	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
429	1	1	0	N/A	N/A	1	1	1	Good	manholr in sidewalk	6/29/2018	1	NO	Local
430	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
431	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
432	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
433	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
434	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
435	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
436	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
437	1	1	0	N/A	N/A	1	1	1	Good	utility box as sidewalk	6/29/2018	1	NO	Local
438	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
439	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
440	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
441	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
442	1	1	0	N/A	N/A	1	1	0	Fair	Light post heaved upwards.	6/29/2018	2	NO	Local
443	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
444	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
445	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
446	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
447	1	1	1	N/A	N/A	1	1	1	Fair	1.5" or greater gap	6/29/2018	0	YES	Local
448	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
449	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
450	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
451	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap.	6/29/2018	2	NO	Local
452	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
453	1	1	N/A	N/A	N/A	0	1	1	Good		6/29/2018	1	NO	Local
454	1	1	0	N/A	N/A	1	1	0	Good	10" - 12" drop along the edge	6/29/2018	2	NO	Local
455	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
456	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
457	1	1	0	N/A	N/A	1	1	0	Good	1.5" or greater gap.	6/29/2018	2	NO	Local
458	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
459	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
460	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
461	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
462	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
463	1	1	0	N/A	N/A	1	1	0	Good	1.5" gap or greater. Most of the sidewalk is new.	6/29/2018	2	NO	Local
464	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
465	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
466	1	1	0	N/A	N/A	1	0	0	Good	sidewalk good but upheaving in a few spots	6/29/2018	3	NO	Local
467	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
468	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
469	1	1	0	N/A	N/A	1	0	1	Fair	Tree roots heaving up sidewalk	6/29/2018	2	NO	Local
470	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
471	1	1	0	N/A	N/A	1	1	1	Fair	a lot of grass on the northern portion	6/29/2018	1	NO	Local
472	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gap.	6/29/2018	2	NO	Local
473	1	1	0	N/A	N/A	1	1	1	Good	mostly new sidewalk	6/29/2018	1	NO	Local
474	1	1	0	N/A	N/A	1	1	0	Poor	Vegetation growth in the cracks of the sidewalk. 1.5" or greater gap. Sidewalk is not complete.	6/29/2018	2	NO	Local
475	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
476	1	1	0	N/A	N/A	1	1	0	Fair	1.5" or greater gaps. Vegetation growth in the cracks of the sidewalk.	6/29/2018	2	NO	Local
477	1	1	0	N/A	N/A	1	1	1	Good	good portion is new concrete	6/29/2018	1	NO	Local
478	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
479	1	1	0	N/A	N/A	1	1	1	Good	mostly new concrete	6/29/2018	1	NO	Local
480	1	1	0	N/A	N/A	1	1	0	Poor	Tree roots heaved up the sidewalk. Vegetation growth in the cracks of the SW. SW isn't complete	6/29/2018	2	NO	Local
481	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk	6/29/2018	1	NO	Local
482	1	1	N/A	N/A	N/A	1	0	1	Good	a lot is slanting to roadway but new concrete	6/29/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
483	1	1	0	N/A	N/A	1	1	1	Fair	longitudinal cracks	6/29/2018	1	NO	Local
484	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
485	1	1	0	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	6/29/2018	1	NO	Local
486	1	1	0	N/A	N/A	1	1	1	Good	all new	6/29/2018	1	NO	Local
487	1	1	0	N/A	N/A	1	1	1	Good	There are a few panels that could be replaced on this block otherwise the SW is new	6/29/2018	1	NO	Local
488	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
489	1	1	0	N/A	N/A	1	1	1	Fair		6/29/2018	1	NO	Local
490	1	1	0	N/A	N/A	1	0	1	Fair		6/29/2018	2	NO	Local
491	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
492	1	1	1	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
493	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
494	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
495	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
496	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
497	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
498	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
499	1	1	1	N/A	N/A	1	1	1	Good	Sidewalk is new. Sidewalk is not complete.	6/29/2018	0	YES	Local
500	1	1	1	N/A	N/A	1	1	0	Good	Sidewalk is new. Sidewalk is not complete.	6/29/2018	1	NO	Local
501	1	1	1	N/A	N/A	1	1	1	Good	Sidewalk is new. Sidewalk is not complete.	6/29/2018	0	YES	Local
502	1	1	1	N/A	N/A	1	1	0	Good	Sidewalk is new. Sidewalk is not complete.	6/29/2018	1	NO	Local
503	1	1	N/A	N/A	N/A	1	1	1	Fair		6/29/2018	0	YES	Local
504	1	1	N/A	N/A	N/A	1	1	1	Fair	a large space between the 2 panels	6/29/2018	0	YES	Local
505	1	1	N/A	N/A	N/A	1	1	0	Fair		6/29/2018	1	NO	Local
506	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
507	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
508	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
509	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
510	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
511	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
512	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
513	1	1	1	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
514	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
515	1	1	N/A	N/A	N/A	1	1	1	Good		6/29/2018	0	YES	Local
516	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
517	1	1	0	N/A	N/A	1	1	1	Good		6/29/2018	1	NO	Local
518	1	1	N/A	N/A	N/A	1	1	1	Fair	brick	7/2/2018	0	YES	Local
519	1	1	N/A	N/A	N/A	1	1	1	Fair	brick with gaps	7/2/2018	0	YES	Local
520	1	1	0	N/A	N/A	1	1	1	Fair		7/2/2018	1	NO	Local
521	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
522	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
523	1	1	1	N/A	N/A	1	0	1		Cross slope is 3.8%	7/2/2018	1	NO	Local
524	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
525	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
526	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap.	7/2/2018	1	NO	Local
527	1	1	N/A	N/A	N/A	1	1	1	Good	giant concrete in middle	7/2/2018	0	YES	Local
528	1	1	0	N/A	N/A	1	1	1	Good		7/2/2018	1	NO	Local
529	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap along the back of curb. Tree overhang onto the sidewalk.	7/2/2018	1	NO	Local
530	1	1	1	N/A	N/A	1	1	1	Fair	Vegetation growth in the cracks of the sidewalk.	7/2/2018	0	YES	Local
531	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap	7/2/2018	1	NO	Local
532	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
533	1	1	1	N/A	N/A	1	1	0	Good		7/2/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
534	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
535	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap.	7/2/2018	1	NO	Local
536	1	1	0	N/A	N/A	1	1	1	Good	1 inch gap	7/2/2018	1	NO	Local
537	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
538	1	1	0	N/A	N/A	1	0	1	Fair		7/2/2018	2	NO	Local
539	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap	7/2/2018	1	NO	Local
540	1	1	1	N/A	N/A	1	1	1	Good	Vegetation growth in the cracks of the sidewalk.	7/2/2018	0	YES	Local
541	1	1	0	N/A	N/A	1	1	1	Fair	utility box in sidewalk	7/2/2018	1	NO	Local
542	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
543	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
544	1	1	N/A	1	0	1	1	1	Good		7/2/2018	1	NO	Local
545	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
546	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
547	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
548	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
549	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
550	1	1	N/A	N/A	N/A	1	0	1	Fair		7/2/2018	1	NO	Local
551	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
552	1	1	1	N/A	N/A	0	1	0	Good	Running slope 5.2%	7/2/2018	2	NO	Local
553	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
554	1	1	N/A	N/A	N/A	1	1	1	Fair	after bridge trail is not existant	7/2/2018	0	YES	Local
555	1	1	1	N/A	N/A	1	0	1	Fair	Cross slope is 2.1%	7/2/2018	1	NO	Local
556	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
557	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
558	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
559	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
560	1	1	1	N/A	N/A	1	0	1	Good	There's a culvert running underneath the Shared Use Path here causing a dip in the pavement. 2.9% Cross slope.	7/2/2018	1	NO	Local
561	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
562	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
563	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
564	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
565	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
566	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
567	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
568	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
569	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
570	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
571	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
572	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
573	1	1	1	N/A	N/A	1	1	1	Good	Shared Use Path has a dip in it that is holding water.	7/2/2018	0	YES	Local
574	1	1	N/A	N/A	N/A	1	1	1	Fair		7/2/2018	0	YES	Local
575	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
576	1	1	1	N/A	N/A	1	1	1	Good	Brush overhang onto shared use path.	7/2/2018	0	YES	Local
577	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
578	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
579	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
580	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
581	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap	7/2/2018	1	NO	Local
582	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
583	1	1	N/A	N/A	N/A	1	0	1	Good	around curve so probabky some superelevation	7/2/2018	1	NO	Local
584	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
585	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap	7/2/2018	1	NO	Local

OBJECTID	Is the route stable, firm and slip-resistant?	Is the route at least 48in wide?	If the sidewalk is 200ft or more by 60in of less, is there a 60 in by 60in passing space?	If there are grates or openings are the openings 0.5 in or less?	Is the long dimension of grate opening perpendicular to the direction of travel?	Is the Running slope 5.0% or less?	Is the cross slope	Are there no gaps in elevation or distance between concrete panels >1.5"?	What is the overall condition of the sidewalk?	Notes	EditDate	# Non Compliant	Compliant	Jurisdiction
586	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
587	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
588	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
589	1	1	N/A	N/A	N/A	1	1	0	Good	1.5" or greater gap.	7/2/2018	1	NO	Local
590	1	1	N/A	N/A	N/A	1	0	1	Good		7/2/2018	1	NO	Local
591	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
592	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap.	7/2/2018	1	NO	Local
593	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
594	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
595	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
596	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
597	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
598	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
599	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
600	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
601	1	1	1	N/A	N/A	1	1	0	Good	1.5" or greater gap	7/2/2018	1	NO	Local
602	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
603	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
604	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
605	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
606	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
607	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
608	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
609	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
610	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
611	1	1	N/A	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
612	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
613	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
614	1	1	1	N/A	N/A	1	1	1	Good		7/2/2018	0	YES	Local
615	1	1	0	N/A	N/A	1	1	1	Good		7/2/2018	1	NO	Local

TOTAL:	601
# Compliant:	162
% Compliant:	27%

OBJECTID	BS_ID	Compliant	Location	Access_Rou	Board_Ligh	Slip_Resis	Perp96inWi	Para60inWi	ParaSlopeM	PerpSlope2	Route_Sign	Shelter	Access_She	Shelter30x	Adj_PAR	SheltFloor	SheltAppr3	Condition
1	BS_01	No	Across from Campbell Library	Y	Y	Y	Y	Y	Y	N	Y	Y	Y	Y	Y	Y	Y	FAIR
2	BS_02	No	Sunshine Terrace	Y	Y	Y	Y	Y	Y	N	Y	Y	Y	Y	Y	Y	Y	FAIR
3	BS_03	No	20th St NE by Tech College	Y	Y	Y	Y	Y	Y	N	Y	Y	Y	Y	Y	Y	Y	GOOD
4	BS_04	Yes	5th Ave NE by Itts William Park	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	GOOD
5	BS_05	No	5th Ave NE by Apartments	Y	Y	Y	Y	Y	Y	N	N	Y	Y	Y	Y	Y	Y	POOR
7	BS_07	No	3rd Ave NW	Y	Y	Y	Y	Y	N	N	Y	Y	Y	Y	Y	Y	Y	POOR

TOTAL:	6
# Compliant:	1
% Compliant:	17%

Curb Ramps

TOTAL:	937
# Compliant:	158
% Compliant:	17%

Overall Compliance

TOTAL:	1582
# Compliant:	344
% Compliant:	22%

Sidewalk

TOTAL:	601
# Compliant:	162
% Compliant:	27%

Bus Shelter Stops

TOTAL:	6
# Compliant:	1
% Compliant:	17%

APS

TOTAL:	44
# Compliant:	24
	0
% Compliant:	55%

System Correction	Unit Cost	Unit	# of non-compliant points collected	% Compliant	Cost
Replace Existing Curb Ramp	\$2,500.00	EA	779	17%	\$1,947,500.00
Replace Concrete Sidewalk	\$10.00	SF	439	27%	\$4,390.00
Replace Accessible Pedestrian Signal	\$1,500.00	EA	20	55%	\$30,000.00
TOTAL:			1,238		\$1,981,890.00

Curb Ramps: \$1,750 - \$2,500 each ramp

Sidewalk: \$8 - \$10 per SF 4" concrete

APS: \$8,000 - \$12,000 (low end is for adding 8 APS buttons, the high end is for including buttons and ped stations)

Based on an 8 button intersection

All cost estimates were based on information used in 2018 Moorhead ADA Transition Plan

Bus Shelter Stops

System Correction	Unit Cost	Unit	# of non-compliant points collected	Cost
Replace Curb & Gutter	\$60.00	LF	120	\$7,200.00
Replace Concrete Sidewalk	\$10.00	SF	1000	\$10,000.00
Replace Detectable Warning Panel	\$500.00	EA	6	\$3,000.00
Total				\$20,200.00